



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8059M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	1,969.50	1,855.00
1	TAILGATE LOGO	NECESSARY	75.00	75.00
1	REAR BUMPER	BUCKLED / CRACKED	455.00	455.00
1	RH REAR BUMPER SIDE RETAINER	DISTORTED	52.97	52.97
1	RH TAILLAMP LOWER GARNISH	DENTED	146.50	146.50
	LESS 25% DISCOUNT		-674.74	-646.12
			2,024.23	1,938.35
	<u>SPECIAL NETT ITEMS</u>			
1	70KM/H STICKER (SN)	NECESSARY	25.00	12.00
10	REAR BUMPER CLIP @\$4.00 (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	TAILGATE STICKER (COMPANY STICKER)(SN)	NECESSARY	200.00	100.00
			465.00	152.00
	<u>LABOUR</u>			
	TO REMOVE/REFIX TAILGATE GLASS.		120.00	120.00
	TO REMOVE/REFIX TAILGATE MECHANISM.		100.00	60.00
	TO FIT REVERSE SENSOR INTO NEW BUMPER AND CHECK WIRING.		50.00	20.00
	TO STRAIGHTEN REAR END PANEL INCLUDING REPLACEMENT OF PARTS.		700.00	400.00
	TO SPRAY PAINT ON TAIL GATE,REAR END PANEL,REAR BUMPER RH TAILLAMP LOWER PANEL.		900.00	700.00
			1,870.00	1,300.00
	GRAND TOTAL		4,359.23	3,390.35

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	-----------------

Report Ref No. CS/AGI21011473/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.