

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21011473/Kvf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	07/12/2021	
			C	ode:	AGI	
1.		Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMF 3982K	Veh. Inspected		GBH 8059M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10012408/JM	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		10/11/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JTFHT02P700245289	Colour		WHITE	
	Odometer	78340 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15X8	HANKOOK		9 mm	
	L/H Front Tyre	195 R15X8	HANKOOK		9 mm	
	R/H Rear Tyre	195 R15X8	HANKOOK		9 mm	
	L/H Rear Tyre	195 R15X8	HANKOOK		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/11/2021	Inspection Date		22/11/2021	
	Survey held at	at FALCON-AIR AUTO SERVICES PTE LTD (HQ)				
		176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: