

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21011475/RTF3E2
Date: 28/03/2022

REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|---------------------------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | MSD/VMS/21-423321-CA |
| Claimant Vehicle No : | SMS593B | Insured Vehicle No : | FBJ3297P |
| Date of Loss: | 03/11/2021 | Nature of Claim: | TP |
| | | | Claim No: MSC/V/21-000479 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SMS593B | | |
| Make & Model: | HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) | Engine No: | L15B31021111 |
| Reg. Date: | 11/07/2016 (Man. Year: 2016) | Chassis No: | JHMGK5850GX202755 |
| Colour: | Red | Odometer: | 61823 km |
| Engine Capacity: | 1498 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 185/55 R16 | Rear Tyre Size: | 185/55 R16 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|---------------|-----------------|--------------|
| Parts | 1,577.28 | 520.00 | 1,057.28 | 67.03 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,800.00 | 400.00 | 1,400.00 | 77.78 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,377.28 | 920.00 | 2,457.28 | 72.76 |
| Approved Total (Overridden) (S\$) | | 700.00 | | |
| (S\$) | 3,377.28 | 700.00 | 2,677.28 | 79.27 |
| + GST 7.00/7.00% (S\$) | 236.41 | 49.00 | 187.41 | 79.27 |
| Nett Amount (S\$) | 3,613.69 | 749.00 | 2,864.69 | 79.27 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 10/11/2021 | | |
| Date Inspected: | 12/11/2021 | Inspected At: | Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856 |
| Estimated Period of Repair: | 2.0 days | | |

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Mar 2022)

Parts: 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SMS593B/28/03/2022 14:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------|---------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 329.40 FL | *329.40 FL |
| 2 | 1 | | *REAR BUMPER GARNISH LH | Cracked | 45.60 FL | *45.60 FL |
| 3 | 1 | | *REAR BUMPER SIDE RETAINER LH | Not Necessary | 55.70 FL | *- FL |
| 4 | 1 | | *REAR BUMPER SIDE RETAINER RH | Not Necessary | 55.70 FL | *- FL |
| 5 | 1 | | *REAR END PANEL | Not Necessary | 540.50 FL | *- FL |
| 6 | 1 | | *REAR TAILLAMP LH | Not Necessary | 540.50 FL | *- FL |
| 7 | 1 | | *REAR TAILLAMP LOWER PANEL LH | Not Necessary | 129.20 FL | *- FL |
| 8 | 1 | | *REAR BUMPER CLIPS | Necessary | 20.00 FS | *20.00 FS |
| 9 | 1 | | *REAR BUMPER SENSOR | Cracked | 200.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|---------------|
| Sub Total (\$) | 1,916.60 | 595.00 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 339.32 | 75.00 |
| Total Parts (\$) | 1,577.28 | 520.00 |

LKK Auto Consultants Pte Ltd/SMS593B/28/03/2022 14:05. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS | New | 1,000.00 | 200.00 |
| 2 | TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS, CLEANING & SANDING OF SURFACES, FINAL POLISHING & WAXING ARE ALSO AVAILABLE | New | 800.00 | 200.00 |
| Gross Labour Cost (\$\$) | | | 1,800.00 | 400.00 |

LKK Auto Consultants Pte Ltd/SMS593B/28/03/2022 14:05. Not valid without Reference section.

< END OF ESTIMATES >