

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011487/TQY3E2

Date: 26/04/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00010522100		
Claimant Vehicle No :	SKA785H	Insured Vehicle No :	SLS8894S		
Date of Loss:	06/11/2021	Nature of Claim:	TP	Claim No:	SNM21D206412/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA785H	Engine No:	1NZY121368
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305174323
Reg. Date:	19/01/2011 (Man. Year: 2010)	Odometer:	164430 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,599.67	4,118.62	11,481.05	73.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	2,420.00	4,080.00	62.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,099.67	6,538.62	15,561.05	70.41
Approved Total (Overridden) (\$\$)		5,200.00		
(\$\$)	22,099.67	5,200.00	16,899.67	76.47
+ GST 7.00/7.00% (\$\$)	1,546.98	364.00	1,182.98	76.47
Nett Amount (\$\$)	23,646.65	5,564.00	18,082.65	76.47

INSPECTION

Date of Assignment:	10/11/2021	
Date Inspected:	10/11/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA785H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	754.60 FL	*568.30 FL
2	1		*BOOTLID LOGO	Necessary	89.00 FL	*59.00 FL
3	1		*BOOTLID EMBLEM (VIOS)	Necessary	76.00 FL	*59.30 FL
4	1		*BOOTLID EMBLEM (E)	Necessary	56.00 FL	*56.00 FL
5	1		*BOOTLID OUTER GARNISH	Cracked	225.80 FL	*128.60 FL
6	2		*BOOTLID CAR PLATE LAMP	Distorted	136.00 FL	*136.00 FL
7	2		*BOOTLID STOPPER	Not Necessary	60.00 FL	*- FL
8	1		*BOOTLID INNER LOCK	Bent	319.50 FL	*106.20 FL
9	1		*BOOTLID LOCK CATCH	Not Necessary	36.00 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Cut	198.60 FL	*168.00 FL
11	4		*BOOTLID STOPPER	Not Necessary	120.00 FL	*- FL
12	2		*BOOT LID HINGE	N/S Not Necessary / O/S Repair	435.00 FL	*- FL
13	1		*REAR BUMPER	Necessary	489.00 FL	*489.00 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	179.00 FL	*179.00 FL
15	2		*REAR BUMPER ATTACHMENT RETAINER	Not Necessary	157.80 FL	*- FL
16	2		*REAR BUMPER REFLECTOR	Cracked	152.80 FL	*152.80 FL
17	2		*REAR BUMPER BRACKET	Not Necessary	270.00 FL	*- FL
18	2		*TAILLAMP	Cracked	970.00 FL	*640.00 FL
19	2		*TAILLAMP PANEL	N/S Not Necessary / O/S Repair	704.00 FL	*- FL
20	2		*TAILLAMP INNER SPONGE SEAL	Necessary	90.00 FL	*90.00 FL
21	2		*TAILLAMP LOWER BRACKET	Bent	134.40 FL	*134.40 FL
22	1		*REAR WINDSCREEN MOULDING	Not Necessary	215.00 FL	*- FL
23	2		*REAR FENDER	N/S Not Necessary / O/S Repair	1,908.00 FL	*- FL
24	2		*REAR FENDER TOP RAILING PANEL	Not Necessary	310.00 FL	*- FL
25	2		*REAR FENDER INNER COWLING	Torn	389.20 FL	*122.20 FL
26	2		*REAR FENDER INNER TRIM	Not Necessary	536.00 FL	*- FL
27	2		*REAR FENDER AIR VENT	Not Necessary	112.00 FL	*- FL
28	1		*REAR END PANEL	Bent	548.00 FL	*380.40 FL
29	1		*REAR END PANEL TOP GARNISH	Deformed	178.50 FL	*178.50 FL
30	1		*REAR FLOOR PANEL	Repair	845.00 FL	*- FL
31	1		*REAR FLOOR PANEL TOP BOARD	Deformed	499.00 FL	*185.10 FL
32	1		*REAR CENTER TOOL SPONGE	Deformed	374.50 FL	*315.00 FL
33	2		*REAR SIDE TOOL SPONGE	Deformed	475.80 FL	*254.40 FL
34	1		*REAR EXHAUST PIPE	Bent	595.40 FL	*549.30 FL
35	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	177.00 FL	*- FL
36	2		*REAR DOOR	Repair	1,569.00 FL	*- FL
37	1		*REAR DOOR INNER LOCK	Not Necessary	496.00 FL	*- FL
38	1		*REAR DOOR LOCK CATCH	Not Necessary	56.00 FL	*- FL
39	1		*REAR DOOR WEATHERSTRIP	Not Necessary	198.00 FL	*- FL
40	1		*DRIVER SEAT BELT	Not Necessary	958.00 FL	*- FL
41	1		*PASSENGER SEAT BELT	Not Necessary	985.00 FL	*- FL
42	1		*SRS AIR BAG CONTOR UNIT	Not Necessary	1,254.00 FL	*- FL
43	1		*BOOTLID OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
45	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
46	1		*TAIL LAMP CLIPS	Necessary	30.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAIL LAMP PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
48	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*REAR FENDER COWLING CLIPS	Necessary	30.00 FS	*20.00 FS
50	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
51	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
52	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
53	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
54	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*40.00 FS
55	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
56	1		*REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
57	1		*REVERSE CAMERA	Not Necessary	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,182.90	5,356.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,583.23	1,237.88
Total Parts (\$\$)	15,599.67	4,118.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	100.00	30.00
5	REMOVE AND INSTALL REAR DOOR PART	New	180.00	0.00
6	REMOVE AND INSTALL REAR WINDSCREEN	New	250.00	120.00
7	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	0.00
8	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILIATE REPAIR	New	300.00	60.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	30.00
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	200.00	30.00
11	REAR CHASSIS ALIGNMENT	New	300.00	0.00
12	TRANSFER BOOTLID MECHANISM	New	120.00	60.00
13	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
14	REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	60.00
15	REMOVE AND REFIX SEAT BELT AND RE-PROGRAM SRS AIRBAG SYSTEM	New	500.00	0.00
Gross Labour Cost (\$\$)			6,500.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >