

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011494/ETY3N2**Date:** 27/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00029222101

Claimant Vehicle No : SMQ6593Y **Insured Vehicle No :** GBJ3231D

Date of Loss: 05/11/2021 Nature of Claim: TP Claim No: SNM21D206355/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ6593Y**

Make & Model: MINI ONE, 1.5 5DR LED (A) Engine No: F466H515B38A12A

Reg. Date: 29/08/2017 (Man. Year: 2017) Chassis No: WMWXS120802G64661

Colour: Orange Odometer: 45676 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm

Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,652.91 | 2,117.24 | 535.67 | 20.19 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,750.00 | 4,450.00 | 3,300.00 | 42.58 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 10,402.91 | 6,567.24 | 3,835.67 | 36.87 |
| + GST 7.00/7.00% (S\$) | 728.20 | 459.71 | 268.49 | 36.87 |
| Nett Amount (S\$) | 11,131.11 | 7,026.95 | 4,104.16 | 36.87 |

INSPECTION

Date of Assignment: 10/11/2021

Date Inspected: 10/11/2021 Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 24 Dec 2021) |
| Parts: | 144 | MINI ONE 1.5 5DR LED (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMQ6593Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT FENDER LH | Dented | 530.14 FS | *530.14 FS |
| 2 | 1 | | *BRACKET,FENDER LH | Not Necessary | 24.83 FS | *- FS |
| 3 | 1 | | *BRACKET,SIDE TOP LH | Not Necessary | 38.29 FS | *- FS |
| 4 | 1 | | *BRACKET,SIDE TOP COLUMN A | Not Necessary | 38.29 FS | *- FS |
| 5 | 1 | | *BRACKET,FENDER CENTER LH | Not Necessary | 38.29 FS | *- FS |
| 6 | 1 | | *BRACKET,SIDE LOWER LH | Not Necessary | 38.29 FS | *- FS |
| 7 | 1 | | *ADDIT,TURN LIGHT LH | Broken | 67.47 FS | *67.47 FS |
| 8 | 1 | | *FRONT DOOR LH | Dented | 1,223.24 FS | *1,223.24 FS |
| 9 | 1 | | *LEFT UPPER HINGE | Not Necessary | 73.19 FS | *- FS |
| 10 | 1 | | *LEFT LOWER HINGE | Not Necessary | 73.19 FS | *- FS |
| 11 | 1 | | *DOOR CHECKER LH | Not Necessary | 90.68 FS | *- FS |
| 12 | 1 | | *BOLT FOR CHECKER | Necessary | 1.89 FS | *1.89 FS |
| 13 | 1 | | *BOLT FOR CHECKER | Necessary | 3.51 FS | *3.51 FS |
| 14 | 1 | | *SOUND INSULATION FOR DOOR | Necessary | 91.85 FS | *91.85 FS |
| 15 | 1 | | *SEAL A-PILLAR LH | Not Necessary | 63.38 FS | *- FS |
| 16 | 1 | | *FRONT FENDER ARCH LH | Cut | 179.14 FS | *179.14 FS |
| 17 | 1 | | *SEAL SIDE FRONT SPONGE | Not Necessary | 27.24 FS | *- FS |
| 18 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|-----------------|-----------------|
| Total Parts (\$\$) | 2,652.91 | 2,117.24 |
|---------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE FRT FENDER LH,FRT DOOR LH & ALL ACCIDENT DAMAGE PARTS.TO REPAIR FRONT A-PILLAR LH & ALL AREAS AFFECTED BY THE ACCIDENT | New | 2,940.00 | 1,680.00 |
| 2 | TO RESPRAY FRT FENDER LH,FRT DOOR LH,FRT A-PILLAR LH | New | 2,600.00 | 1,600.00 |
| 3 | TO CARRY-OUT BODY CAVITY PRESERVATION | New | 250.00 | 150.00 |
| 4 | TO TRANSFER THE FRONT DOOR RH MECHANISM | New | 420.00 | 420.00 |
| 5 | TO MOUNT THE CAR ONTO CELETTE BENCH TO GIVE WAY ON THE REPAIR OF THE A-PILLAR | New | 840.00 | 0.00 |
| 6 | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING | New | 250.00 | 150.00 |
| 7 | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS | New | 350.00 | 350.00 |
| 8 | TO TOW THE CAR FROM THE ACCIDENT SITE TO THE WORKSHOP | New | 100.00 | 100.00 |
| Gross Labour Cost (\$) | | | 7,750.00 | 4,450.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >