



EUROKARS HABITAT PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042



FINALIZE COST OF REPAIRS

China Taiping Insurance (Singapore) Pte		NAME :		WIP : 49768	
3 Anson Road		ADDRESS :		EXCESS :	
#16-00 Springleaf Tower				DATE: 9-Nov-21	
Singapore 079909		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SMQ6593Y	DATE IN :		CONTACT PERSON :	JESS 8128 9802
CHASSIS NO :	WMWXS120802G64661	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	MINI One 5 Door RHD	DATE REG.	29-Aug-17	POLICY NO. :	

NATURE OF WORKS									
Parts Description		QTY	UNIT PRICE	DISC(%)	1ST	SUPP		REVISED	PRICES
1	FRONT FENDER LH	TBA	1	530.14	-	✓	M41.00.7.374.521	530.14	530.14
2	BRACKET, FENDER LH	TBA	1	24.83	-		M41.00.7.374.527		24.83
3	BRACKET, SIDE TOP LH	TBA	1	38.29	-		M41.00.7.389.471		38.29
4	BRACKET, SIDE TOP COLUMN A	TBA	1	38.29	-		M41.00.7.389.467		38.29
5	BRACKET, FENDER CENTER LH	TBA	1	38.29	-		M41.00.7.389.466		38.29
6	BRACKET, SIDE LOWER LH	TBA	1	38.29	-		M41.00.7.389.489		38.29
7	ADDIT. TURN LIGHT LH	TBA	1	67.47	-	✓	M63.13.7.298.347	67.47	67.47
8	FRONT DOOR LH	TBA	1	1,223.24	-	✓	M41.00.7.327.445	1,223.24	1,223.24
9	LEFT UPPER HINGE	TBA	1	73.19	-		B41.51.7.284.533		73.19
10	LEFT LOWER HINGE	TBA	1	73.19	-		B41.51.7.284.535		73.19
11	DOOR CHECKER LH	TBA	1	90.68	-		M51.21.7.328.595		90.68
12	BOLT FOR CHECKER	EX	1	1.89	-	✓	B51.22.6.976.687	1.89	1.89
13	BOLT FOR CHECKER	EX	1	3.51	-	✓	B07.14.7.248.303	3.51	3.51
14	SOUND INSULATION FOR DOOR	TBA	1	91.85	-	✓	M51.48.7.386.607	91.85	91.85
15	SEAL, A-PILLAR LH	TBA	1	63.38	-		M51.76.7.322.455		63.38
16	FRONT FENDER ARCH LH	EX	1	179.14	-	✓	M51.77.7.300.819	179.14	179.14
17	SEAL, SIDE FRONT SPONGE	TBA	1	27.24	-		M51.48.7.298.941		27.24

SUPPLEMENTARY									
NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1ST	SUPP	PARTS NO	REVISED	PRICES
1									
2									
3									
TOTAL PARTS								2,097.24	2,602.91
								-	
TOTAL PARTS COST								2,097.24	2,602.91

Labour Description				
1	REPLACE LHF DOOR, LHF FENDER. REPAIR AREAS AFFECTED BY THE ACCIDENT.		1,680.00	2,940.00
2	SPRAY LHF FENDER, LHF DOOR.		1,600.00	2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.		150.00	250.00
4	TO TRANSFER THE TRANSFER THE FRONT DOOR RH MECHANISM.		420.00	420.00
5	TO MOUNT THE CAR ONTO CELETTE BENCH TO GIVE WAY ON THE REPAIR OF THE A-PILLAR		-	840.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150.00	250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	350.00

8	SUNDRIES.	20.00	50.00
<u>SUPPLEMENTARY LABOUR</u>			
1	TO TOW THE CAR FROM THE ACCIDENT SITE TO THE WORKSHOP.	100.00	100.00
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.	TOTAL LABOUR	4,470.00	7,700.00
	TOTAL PARTS	2,097.24	2,602.91
	TOTAL	6,567.24	10,302.91
	LESS EXCESS	-	-
	TOTAL AFTER EXCESS	6,567.24	
	GST 7%	459.71	-
	GRAND TOTAL	7,026.95	-

SURVEYED BY : STEVE OF LKK ON 10-11-2021

REPAIR DAYS : 4 DAYS