



EUROKARS HABITAT PTE LTD

27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

China Taiping Insurance (Singapore) Pte		NAME :		WIP :	
3 Anson Road		ADDRESS :		EXCESS :	
#16-00 Springleaf Tower				DATE :	
Singapore 079909		TEL :		9-Nov-21	
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SMQ6593Y	DATE IN :		CONTACT PERSON :	JESS 8128 9802
CHASSIS NO :	WMWXS120802G64661	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	MINI One 5 Door RHD	DATE REG.:	29-Aug-17	POLICY NO. :	

NATURE OF WORKS

Parts Description	QTY	UNIT PRICE	DISC(%)	1ST	SUPP		REVISED	PRICES
1 FRONT FENDER LH <i>00</i>	1	530.14	-			M41.00.7.374.521		530.14
2 BRACKET, FENDER LH <i>x nn</i>	1	24.83	-			M41.00.7.374.527		24.83
3 BRACKET, SIDE TOP LH <i>x nn</i>	1	38.29	-			M41.00.7.389.471		38.29
4 BRACKET, SIDE TOP COLUMN A <i>x nn</i>	1	38.29	-			M41.00.7.389.467		38.29
5 BRACKET, FENDER CENTER LH <i>x m</i>	1	38.29	-			M41.00.7.389.466		38.29
6 BRACKET, SIDE LOWER LH <i>x nn</i>	1	38.29	-			M41.00.7.389.489		38.29
7 ADDIT. TURN LIGHT LH <i>BR</i>	1	67.47	-			M63.13.7.298.347		67.47
8 FRONT DOOR LH <i>nn</i>	1	1,223.24	-			M41.00.7.327.445		1,223.24
9 LEFT UPPER HINGE <i>x nn</i>	1	73.19	-			B41.51.7.284.533		73.19
10 LEFT LOWER HINGE <i>x nn</i>	1	73.19	-			B41.51.7.284.535		73.19
11 DOOR CHECKER LH <i>x nn</i>	1	90.68	-			M51.21.7.328.595		90.68
12 BOLT FOR CHECKER <i>nk</i>	1	1.89	-			B51.22.6.976.687		1.89
13 BOLT FOR CHECKER <i>nk</i>	1	3.51	-			B07.14.7.248.303		3.51
14 SOUND INSULATION FOR DOOR <i>nk</i>	1	91.85	-			M51.48.7.386.607		91.85
15 SEAL, A-PILLAR LH <i>x nn</i>	1	63.38	-			M51.76.7.322.455		63.38
16 FRONT FENDER ARCH LH <i>cut</i>	1	179.14	-			M51.77.7.300.819		179.14
17 SEAL, SIDE FRONT SPONGE <i>x nn</i>	1	27.24	-			M51.48.7.298.941		27.24

TOTAL PARTS

2,602.91

TOTAL PARTS COST

2,602.91

SUPPLEMENTARY

NO	DESCRIPTION	QTY	UNIT PRICE	DISC(%)	1ST	SUPP	PARTS NO	REVISED	PRICES
1									
2									
3									

Labour Description

1	TO REPLACE FRT FENDER LH, FRT DOOR LH & ALL ACCIDENT DAMAGE PARTS . TO REPAIR FRONT A-PILLAR LH & ALL AREAS AFFECTED BY THE ACCIDENT. <i>840 x 2</i>							1680	2,940.00
2	TO RESPRAY FRT FENDER LH, FRT DOOR LH, FRT A-PILLAR LH . <i>800 x 2</i>							1600	2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.							150	250.00
4	TO TRANSFER THE FRONT DOOR RH MECHANISM.							NETT	420.00

	TO MOUNT THE CAR ONTO CELETTE BENCH TO GIVE WAY ON THE REPAIR OF THE A-PILLAR	NETT	840.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	350.00
8	SUNDRIES.	NETT	50.00
		TOTAL LABOUR	7,700.00
		TOTAL PARTS	2,602.91
		TOTAL	10,302.91
		LESS EXCESS	-
		TOTAL AFTER EXCESS	-
		GST 7%	-
		GRAND TOTAL	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Stere (CLKK)
10/11/21, 4.19p-

wh RL
P/P
M BK M
4 Lys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company