PRECISION APPRAISAL SERVICES



Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers 227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

To:LENG YONG MOTOR WORKSHOP
C/O 27A Jurong Port Rd, #01-28,
Singapore 619101

Invoice No.: 211184

DATE: 01 November 2021

DOLLARS	FOUR HUNDRED & EIGHTY ONLY TOTAL:	\$480.00
Additional Photographs Others (Specify)	: -	
Transportation Charge	• -	
Reinspection Report Fe		
Inspection Report Fees	: (including transportation charges & photographs)	\$480.00
Your Reference No.	: -	
Our Reference No.	: PAS/LYM/211184/TP	
Type of Claims	: Third Party Claims	
Vehicle Registration N	。. : GBB 7743 J	
	DL30KIF I ION	Amount
	DESCRIPTION	AMOUNT



PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/Adjusters Cargo Surveyors & Licensed Appraisers 227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION

To:

LENG YONG MOTOR WORKSHOP C/O 27A Jurong Port Rd, #01-28, Singapore 619101

INSURANCE DETAILS

Insured

Policy No. / Claim No. : -

Sum Insured

Excess Clause

Windscreen Coverage : -

Type of Claims

: Third Party Claims

Third Party Insurer : -

Third Party Policy No.: -

REFERENCE

Assigned By

: As above

Accident Date

: 12 October 2021

Assignment Date

: 12 October 2021

Inspection Date

: 12 October 2021

Our Reference No. : PAS/LYM/211184/TP

Inspection Report Date: 01 November 2021

Workshop Name:

LENG YONG MOTOR WORKSHOP

Inspection Address:

27A Jurong Port Rd #01-28 Singapore 619101

PARTICULARS OF VEHICLE

Registration No.

: GBB 7743 J

Make/Model

: TOYOTA DYNA 150 MANUAL 3SEATER

Yr of Manuf/Regn

: 27 Jan 2010

Carrying Capacity : -

Chassis No.

: JTFAT35Y90K201015

Engine No.

: 1KD1977345

Colour

: Metallic Silver

Class

: Goods (Lorry)

Mileage Radio/Casette CD 442585

Km/h

: Fitted

Disc Player

: Fitted

Air Conditioner

: Fitted

Clock

: Fitted : Fitted

Seat Belt

Wing Mirror

: Fitted

X

X

Other Accessories : Fitted

PRE-ACCIDENT CONDITION (Static Check Only) VEHICLE VALUE

Body Work

: Good

Paint Work

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Any Apparent

Eng Modifications

: None

TYRE SIZE & CONDITION

Front N/s Size : 195R14C

80 %

Front O/s Size

Rear O/s Size

Market Value

Wreck Value (Parf) :

: 195R14C

80 %

Make Rear N/s Size : 155R12C

: MAXMILER

80 %

Make

: MAXMILER 155R12C

80 %

Make

Spare Size

: MAXMILER

80 %

Spare Size

: MAXMILER

: MAXMILER Make

: 195R14C

Make

Make

155R12C : MAXMILER

Type of Wheel Rims: Standard

Jack & Tools

: Intact


Note: The above percentage % represent the estimated remaining tyre threads.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers

VEHICLE REGISTRATION NO. : GBB 7743 J

APPENDIX A



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were: The tailgate and lower panel, rear o/s taillamp panel were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 12/10/2021 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s LENG YONG MOTOR WORKSHOP as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Lump Sum Repair Basis of \$3,250.00 after deducting the Policy Excess Clause of \$NA. As instructed, we have not authorised any of the repairs on your behalf.

		Repairer's		<u>Our</u>		
	Es	timate	Amount	Revised	A	mount
Spares Parts	:	3576	60	2689		95
Towing Charges	:	X	X	Χ		Χ
PB Labour Charges	:	800	00	680		00
Others Misc Charges	:	50	00	30		00
Paintwork	:	800	00	600		00
Total	: \$	5226	60	\$ 4079		95

Under normal circumstances, the duration of repairs should not exceed Nine (09) days including Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame & Public Holidays

Attached photographs taken during inspection Forty (40) Photographs

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis

2. On 20/10/2021, we examined the repaired vehicle.

Yours FaithFully

TFNG PHILIPFOO ACII CAE, AMIMI AIAME, AMSAE-A

Licensed Appraiser/Adjuster

Inspection Report Date: 01 November 2021

VEHICLE REGN NO :

GBB 7743 J

PAS/LYM/211184/TP

OUR REFERENCE : "

1-Nov-21

INSPECTION REPORT DATE:

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO:

S/No Qty		Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation Revised Amou		
,		PARTS SUPPLY - LIST ITEMS		\$ cts	\$ cts		
1	1pc	O/s Taillamp panel	Badly dented	396.70	396.70		
2	1pc	O/s Taillamp holder	Badly dented	211.60	211.60		
3	1pc	O/s Taillamp	Cracked	368.10	368.10		
4	1pc	Tailgate	Badly dented	1280.00	1280.00		
5	4pcs	Tailgate hinges@\$108.1	Bent	432.40	432.40		
6	1pc	Rear lower panel 'Dyna' sticker	Necessary	38.10	38.10		
7	1pc	Tailgate lock o/s	Bent	131.10	131.10		
8	1pc	Rear corner bracket o/s	Bent	196.10	196.10		
9	1pc	Rear corner stopper o/s	Torn	38.10	38.10		
10	1pc	Tailgate lock n/s	Bent	131.10	131.10		
11	1pc	Rear corner bracket n/s	Bent	196.10	196.10		
12	1pc	Rear corner stopper n/s	Torn	38.10	38.10		
13	1pc	Tailgate 'Toyota' sticker	Necessary	89.10	89.10		
		9		3546.60	3546.60		
		Less: 25% discount		-	886.65		
				3546.60	2659.95		
		SPECIAL NETT ITEMS					
1	1pc	Tailgate '70km/h' sticker	Necessary	10.00	10.00		
2	1pc	Rear no. plate	Dented	20.00	20.00		
				3576.60	2689.95		
		LABOUR & MISC. CHARGES					
1		Remove the necessary affected par					
		straighten tailgate lower panel,					
		both rear chassis and replace parts		800.00	680.00		
3		Putty and Spraypaint on all affected parts		800.00	680.00		
4		Rewire rear portion		50.00	30.00		
		Note: Recommended lump sum					
		repair at \$3,250.00nett			_		
			SUB / GRAND TOTAL	5226.60	4079.95		

PRECISION APPRAISAL SERVICES

a visit

































































