

### ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: GBJ9289Z

Chassis No:

Engine No:

MAKE: Toyota

MODEL: Hiace

Report No :

Date : 11.11.2021

TYPE : COMMERCIAL

#### Replacement of Damaged Parts

<u>S/No.</u>	<u>Quantity</u>	<u>Description</u>	<u>Repairer's Estimates</u>	<u>Our Recommendation</u>
1	1	Centre Door ✓ BUC	\$ 2,395.38	\$ 1,916.30
			\$ 2,395.38	\$ 1,916.30

1255.95

Total (Parts): \$ 2,395.38 \$ 1,916.30

#### Labour Charges

Disc -25%: 941.96

- \* To dismantle and refit the door fittings/components to the new door shell, adjust of same \$ 500.00 50
- \* To labour charge for dismantle and renew the accident damaged parts To heat/weld, knocking, straighten, repair, adjust of same \$ 500.00 150
- \* Top putty and spray painting on affected area; panel beating of affected area \$ 1,000.00 200

Total Labour: \$ 2,000.00

Total cost of repairs (Total cost of parts + Total Labour Cost) : \$ 3,916.30

1341.96

Lumpsum -20%: 1050

2 Days

Guo Qiang  
82880282

Guo Qiang@lkkauto.com

11/11/21

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul> <p>Acknowledged by Repairer Signature: Date:</p>
--