

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011505/UVF3E2

**Date:** 18/11/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001345896
<b>Claimant Vehicle No :</b>	SMQ5629K	<b>Insured Vehicle No :</b>	GBH2666A
Date of Loss:	10/11/2021	Nature of Claim:	TP
		Claim No:	265255

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5629K	Engine No:	G4FGKU473852
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMLU009936
Reg. Date:	25/11/2019 (Man. Year: 2019)	Odometer:	41455 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,957.36	3,483.44	6,473.92	65.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,650.00	2,250.00	57.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,857.36</b>	<b>5,133.44</b>	<b>8,723.92</b>	<b>62.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,857.36</b>	<b>4,100.00</b>	<b>9,757.36</b>	<b>70.41</b>

### INSPECTION

Date of Assignment:	11/11/2021	
Date Inspected:	11/11/2021	Inspected At: Blk 15 Kaki Bukit Road 4, Bartley bIZ, #01-53
Estimated Period of Repair:	4.0 days	Repairer : Zoom Autowerks Pte Ltd

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
<b>Parts:</b>	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ5629K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Badly Dented	1,853.60 FL	*1,782.00 FL
2	1		*REAR BOOT INNER TRIM	Not Necessary	235.60 FL	*- FL
3	1		*REAR BOOT LAMPS	N/S Cracked /O/S Not Necessary	1,374.60 FL	*294.00 FL
4	1		*REAR BOOT LOCK	Twisted	234.00 FL	*145.00 FL
5	1		*REAR BOOT LOGO	Necessary	169.70 FL	*42.00 FL
6	1		*REAR BOOT RUBBER	Not Necessary	300.30 FL	*- FL
7	1		*REAR BOOT S EMBLEM	Necessary	92.40 FL	*48.00 FL
8	1		*REAR BOOT AVANTE EMBLEM	Necessary	97.90 FL	*35.00 FL
9	1		*REAR TAILLAMPS	N/S Cracked /O/S Not Necessary	2,179.20 FL	*362.50 FL
10	1		*REAR END PANEL	Repair	657.80 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	175.90 FL	*- FL
12	1		*REAR BUMPER	Dented / Torn	459.40 FL	*459.40 FL
13	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	161.80 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
15	1		*REAR BUMPER INNER SPONGE	Not fitted	166.30 FL	*- FL
16	1		*REAR BUMPER REFLECTOR N/S	Cracked	359.00 FL	*202.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	294.80 FL	*294.80 FL
18	1		*REAR BUMPER CENTRE GARNISH	Torn	339.60 FL	*339.60 FL
19	2		*REAR NUMBER PLATE LAMPS	Not Necessary	112.60 FL	*- FL
20	1		*REAR VIEW CAMERA	Not Necessary	582.60 FL	*- FL
21	1		*REAR FLOOR BOARD	Not Necessary	397.80 FL	*- FL
22	1		*REAR FLOOR PANEL	Not Necessary	798.60 FL	*- FL
23	1		*REAR EXHAUST SILENCER	Not Necessary	756.20 FL	*- FL
24	2		*REAR EXHAUST MOUNTINGS	Not Necessary	97.00 FL	*- FL
25	1		*REAR NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS
26	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,346.70</b>	<b>4,294.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,389.34	810.86
<b>Total Parts (\$\$)</b>	<b>9,957.36</b>	<b>3,483.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LIFT MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
6	TO APPLY UNDERCOATING	New	150.00	30.00
7	PANEL BEATING	New	1,600.00	580.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	820.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,900.00</b>	<b>1,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >