

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21011508/T1QF3Q2
Date: 19/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJB1057B	Insured Vehicle No :	GBH6779G
Date of Loss:	10/11/2021	Nature of Claim:	TP
		Claim No:	1663567675SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB1057B		
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Engine No:	HRA2122773A
Reg. Date:	22/04/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1323307
Colour:	Black	Odometer:	126899 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

11/19/21, 5:22 PM

Adjuster Report

Date of Assignment: 11/11/2021

Date Inspected: 11/11/2021 Inspected At:

3 Motorwerkz Concepts Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42
SINGAPORE 417800

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$42,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	*Check	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
8	2		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
9	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
10	1		*REAR END PANEL	Repair	0.00 F	*- F
11	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
13	1		*TAILGATE	Bent	0.00 F	*- F
14	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
15	1		*TAILGATE GARNISH	Deformed	0.00 F	*- F
16	2		*TAILGATE LAMP	Cracked	0.00 F	*- F
17	1		*TAILGATE CAMERA	*Check	0.00 F	*- F
18	1		*TAILGATE GLASS RUBBER	Necessary	0.00 F	*- F
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
20	1		*TAILGATE LOCK	Bent	0.00 F	*- F
21	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
22	1		*TAILGATE DAMPER	*Check	0.00 F	*- F
23	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
24	1		*SPARE TYRE SPONGE	Deformed	0.00 F	*- F
25	1		*REAR RH FENDER PROTECTOR ARCH	Deformed	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >