

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 3026Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FORK SET	SERVICEABLE	550.00	-
1	FORK T-UNDER BRACKET	NOT NECESSARY	400.00	-
1	STEERING CONE	NOT NECESSARY	150.00	-
1	FRONT TYRE SHAFT	NOT NECESSARY	40.00	-
1	HANDLE BAR	BENT	185.00	175.00
1	HANDLE BAR END	CUT	100.00	30.00
1	HANDLE GRIP	TORN	80.00	80.00
1	MIRROR SET	BROKEN	95.00	95.00
1	MASTER PUMP	CUT	190.00	190.00
1	BRAKE LEVEL	BENT / CUT	50.00	50.00
1	HEAD LIGHT	SCRATCHED	750.00	699.00
1	SIGNAL LIGHT	SCRATCHED	250.00	165.00
1	INNER PANEL	CUT	300.00	195.00
1	BODY UNDER COVER	TORN	250.00	145.00
1	FRONT FOOTREST COVER	DISTORTED	185.00	138.00
1	REAR FOOTREST	CUT	150.00	60.00
1	EXHAUST PIPE	DENTED / BENT	950.00	735.00
1	EXHAUST COVER	MISSING	150.00	136.00
1	REAR SWING ARM	NOT NECESSARY	550.00	-
1	FRONT FOOTREST UNDER COVER	DISTORTED	130.00	130.00
1	RIGHT INNER COVER	CUT	120.00	120.00
1	HANDLE COVER	CUT	80.00	80.00
1	COVERSET FULL	CUT	700.00	625.00
1	MAINSTAND	NOT NECESSARY	400.00	-
1	FRONT RIM	NOT NECESSARY	600.00	-
1	FRONT DISC	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-	-384.80
			7,655.00	3,463.20

Report Ref No. CS/SMO21011509/Uqf3n2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR.		700.00	300.00
			700.00	300.00
	GRAND TOTAL		8,355.00	3,763.20

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO21011509/Uqf3n2

CHUA KANG SENG

**Licensed Appraiser**