

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011514/GVY3N2**Date:** 02/12/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00011782100  
**Claimant Vehicle No :** GBJ9140T **Insured Vehicle No :** XE6168A  
 Date of Loss: 09/11/2021 Nature of Claim: TP Claim No: SNM21D206478/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ9140T**  
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 4DR (A) Engine No: 1KDB012555  
 Reg. Date: 07/10/2019 (Man. Year: 2019) Chassis No: JTFHT02P500249616  
 Colour: White Odometer: 57258 km  
 Engine Capacity: 2982 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 2,446.15          | 900.12            | 1,546.03          | 63.20         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,900.00          | 1,970.00          | 930.00            | 32.07         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>5,346.15</b>   | <b>2,870.12</b>   | <b>2,476.03</b>   | <b>46.31</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,300.00</b>   |                   |               |
| <b>(S\$)</b>                             | 5,346.15          | 2,300.00          | 3,046.15          | 56.98         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 374.23            | 161.00            | 213.23            | 56.98         |
| <b>Nett Amount (S\$)</b>                 | <b>5,720.38</b>   | <b>2,461.00</b>   | <b>3,259.38</b>   | <b>56.98</b>  |

INSPECTION

Date of Assignment: 12/11/2021  
 Date Inspected: 11/11/2021 Inspected At: Convince Auto Pte Ltd (HQ)  
 176 SIN MING DRIVE #04-04, SIN MING  
 AUTOCARE  
 Singapore 575721  
 Estimated Period of Repair: 6.0 days

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

|                      |  |  |
|----------------------|--|--|
| <b>Part Source:</b>  | (Last Synchronised: 01 Dec 2021)   |  |
| <b>Parts:</b>        | N/A  | TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBJ9140T)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

**Recommended Parts**

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-----------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER                      | Cracked       | 693.00 FL   | *373.02 FL |
| 2   | 1   |          | *REAR BUMPER SIDE RETAINER RH     | Cut           | 54.30 FL    | *27.90 FL  |
| 3   | 1   |          | *REAR END PANEL                   | Buckled       | 358.20 FL   | *358.20 FL |
| 4   | 1   |          | *TAIL LAMP RH                     | Cracked       | 235.60 FL   | *235.60 FL |
| 5   | 1   |          | *TAIL LAMP LOWER COVER RH         | Missing       | 125.57 FL   | *84.60 FL  |
| 6   | 1   |          | *TAIL LAMP LOWER COVER BRACKET RH | Missing       | 83.45 FL    | *50.84 FL  |
| 7   | 1   |          | *REAR FENDER RH                   | Repair        | 1,583.30 FL | *- FL      |
| 8   | 1   |          | *REAR FENDER AIR VENT RH          | Not Necessary | 58.12 FL    | *- FL      |
| 9   | 10  |          | *REAR BUMPER CLIP                 | Necessary     | 35.00 FS    | *35.00 FS  |
| 10  | 5   |          | *TAIL LAMP LOWER COVER CLIP RH    | Necessary     | 17.50 FS    | *17.50 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>3,244.04</b> | <b>1,182.66</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | 797.89          | 282.54          |
| <b>Total Parts (S\$)</b>                                  | <b>2,446.15</b> | <b>900.12</b>   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars  | Lab.Type | Repairer's                    | Amount          |
|---------------------|--|----------|-------------------------------|-----------------|
| <b>Labour Items</b> |  |          |                               |                 |
| 1                   | TO REPAIR PANEL BEATING,WELDING & STRAIGHTEN DAMAGED PARTS AND REPLACE ABOVE PARTS ON DAMAGED AREA | New      | 1,200.00                      | 1,000.00        |
| 2                   | TO SPRAY PAINTING AFFECTED AREA  | New      | 1,200.00                      | 800.00          |
| 3                   | TO REMOVE & REFIX REVERSE SENSOR   | New      | 120.00                        | 40.00           |
| 4                   | TO APPLY ANTI-RUST   | New      | 150.00                        | 60.00           |
| 5                   | TO CHECK WIRING FUNCTION   | New      | 50.00                         | 30.00           |
| 6                   | TO APPLY JOINT SEALANT   | New      | 100.00                        | 40.00           |
| 7                   | TO CHECK & TEST WATER SEEPAGE  | New      | 80.00                         | 0.00            |
|                     |  |          | <b>Gross Labour Cost (\$)</b> | <b>1,970.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >