

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011521/AVY3N2**Date:** 08/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00198482100

Claimant Vehicle No : SBQ4009L **Insured Vehicle No :** EZ31P

Date of Loss: 25/10/2021 Nature of Claim: TP Claim No: SNM21D206135/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBQ4009L**

Make & Model: LEXUS RX200T, 2.0 (A) Engine No: 8AR4276573

Reg. Date: 15/07/2020 (Man. Year: 2020) Chassis No: JTJZAMCA902082487

Colour: Grey Odometer: 22699 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/65R18 Rear Tyre Size: 235/65R18

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,302.30	1,220.70	3,081.60	71.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	580.00	2,210.00	79.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,092.30	1,800.70	5,291.60	74.61
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	7,092.30	1,400.00	5,692.30	80.26
+ GST 7.00/7.00% (S\$)	496.46	98.00	398.46	80.26
Nett Amount (S\$)	7,588.76	1,498.00	6,090.76	80.26

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 12/11/2021 Inspected At: 51 UBI AVENUE 1
#01-25 PAYA UBI IND.PARK
REPAIRER: SK AUTOMOBILE PTE LTD

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts:	M1-SUV	LEXUS RX200T 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBQ4009L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	991.00 FL	*991.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Not Necessary	49.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR GARNISH RH	Cracked	181.00 FL	*181.00 FL
4	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	708.00 FL	*- FL
5	1		*REAR BUMPER REVERSE SENSOR RH	Not Necessary	488.00 FL	*- FL
6	4		*REAR BUMPER REVERSE SENSOR HOLDER	Not Necessary	80.00 FL	*- FL
7	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS SET	Not Necessary	118.00 FL	*- FL
8	1		*REAR BUMPER EXHAUST END CHROME PIPE RH	Not Necessary	269.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER LH/RH	O/s Necessary	302.00 FL	*151.00 FL
10	2		*REAR BUMPER LOWER SIDE BRACKET LH/RH	Not Necessary	404.00 FL	*- FL
11	1		*REAR BUMPER INNER SPONGE	Not Necessary	128.00 FL	*- FL
12	2		*REAR FENDER ARCH GARNISH LH/RH	Not Necessary	230.00 FL	*- FL
13	1		*REAR FENDER INNER AIR VENT RH	Not Necessary	173.00 FL	*- FL
14	1		*REAR FENDER INNER SHIELD RH	Not Necessary	326.00 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
16	2		*REAR FENDER ARCH GARNISH CLIPS SET LH/RH	Not Necessary	100.00 FS	*- FS
17	2		*REAR FENDER INNER SHIELD CLIPS SET LH/RH	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,747.00	1,353.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	444.70	132.30
Total Parts (\$\$)	4,302.30	1,220.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	750.00	250.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	750.00	250.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	80.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	120.00	30.00
5	TO DISMANTLE REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	150.00	50.00
6	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	380.00	0.00
7	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	New	280.00	0.00
8	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
Gross Labour Cost (\$\$)			2,790.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >