

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011523/EQY3N2**Date:** 28/12/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00008902100
<b>Claimant Vehicle No :</b>	SLL3186Y	<b>Insured Vehicle No :</b>	SMJ7688M
Date of Loss:	08/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206445/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLL3186Y</b>	Engine No:	27091030926797
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A)	Chassis No:	WDD1173422N347209
Reg. Date:	22/06/2016 (Man. Year: 2016)	Odometer:	74925 km
Colour:	Silver		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,567.21	6,378.38	188.83	2.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	4,280.00	1,080.00	20.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>11,927.21</b>	<b>10,658.38</b>	<b>1,268.83</b>	<b>10.64</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	834.90	746.09	88.81	10.64
<b>Nett Amount (\$\$)</b>	<b>12,762.11</b>	<b>11,404.47</b>	<b>1,357.64</b>	<b>10.64</b>

**INSPECTION**

Date of Assignment:	28/11/2021	
Date Inspected:	22/11/2021 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	6.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 27 Dec 2021)

**Parts:** 143      MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLL3186Y)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*LEFT & RIGHT FRONT DISK WHEEL	Cut	1,377.36 FS	*1,377.36 FS
2	1		*LEFT HEADLAMP	Cut	2,632.90 FS	*2,632.90 FS
3	1		*FRONT BUMPER	Broken	1,421.95 FS	*1,421.95 FS
4	1		*FRONT BUMPER MB EMBLEM	Necessary	63.68 FS	*63.68 FS
5	1		*LEFT FRONT DISTANCE SENSOR	Not Necessary	182.48 FS	*- FS
6	1		*PTS SPACER RING	Not Necessary	6.35 FS	*- FS
7	1		*LEFT FRONT FENDER	Dented	683.73 FS	*683.73 FS
8	1		*LEFT FRONT FENDER INTERMEDIATE LAYER	Necessary	17.94 FS	*17.94 FS
9	1		*FRONT BASIC MOUNTING FOR BUMPER	Broken	180.82 F	*180.82 F
					<b>Total Parts (S\$)</b>	<b>6,567.21      6,378.38</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TRANSFER TYRES OVER TO NEW RIMS X2	New	120.00	120.00
2	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	2,400.00	1,920.00
3	RESPRAY FRONT BUMPER AND LEFT FRONT FENDER	New	1,800.00	1,200.00
4	USING XENTRY SYSTEM TO CHECK CONTROL UNITS,RESET SYSTEM TO STANDARD SETTINGS	New	380.00	380.00
5	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
6	INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT	New	540.00	540.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,360.00</b>	<b>4,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >