



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220
Tel: 9101 7844 Fax: 6996 6442

Business Reg. No.: 53387981K
Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/2109/FBP1259G/CKM

ASSESSMENT FOR REPAIR : FBP1259G

Qty	Description	Condition	Repairer's Estimate	Our Assessment	
1 pc	Rear combination light assy	Holder Broken	132.00	132.00	} 160
1 pc	Rear combination light cover	Grazed	46.00	46.00	
1 pc	Rear fender inner	Warped	79.00	79.00	
1 pc	Rear fender upper	Broken	105.00	105.00	✓
1 pc	Rear fender lower	Torn	72.00	72.00	✓
1 pc	License light assy	Broken	47.00	47.00	✓
1 pc	Reflex reflector	Cut	16.00	16.00	✓
1 pc	Swingarm assy repair	Distorted	445.00	445.00	x
1 pc	Swingarm pivot bolt	Distorted	72.00	72.00	✓
1 pc	Rear cushion assy xsvc	Shifted	245.00	245.00	x
1 pc	Rear wheel repair	Deformed	395.00	395.00	x
1 pc	Rear wheel axle	Distorted	52.00	52.00	✓
1 pc	Exhaust muffler complete xsvc	Shifted	630.00	630.00	x
1 pc	Muffler protector xsvc	Grazed	86.00	86.00	x
1 pc	Muffler cap	Cut	44.00	44.00	✓
			2,466.00	2,466.00	647
		Less 10%	246.60	246.60	10%
			2,219.40	2,219.40	582.30
Special Nett Items					
1 pc	Rear tyre 70%	Cut	135.00	135.00	94.50
1 pc	Rear number plate	Deformed	20.00	18.00	15
			155.00	153.00	109.50
Total Parts			2,374.40	2,372.40	
Labour Charges					
1	Towing fee		80.00	60.00	40
2	Repair & straighten body frame rear		600.00	550.00	200
3	Rebalance rear wheel		200.00	150.00	30
4	Spray painting for damaged covers		200.00	180.00	100
5	Renew damaged parts; align swingarm & rear wheel		500.00	450.00	200
			1,580.00	1,390.00	570
Total Parts & Labours Concluded			3,954.40	3,762.40	
Lump Sum Repair Adjustment				3,000.00	
				582.30	
				109.50	
				570.00	
				1261.80	
				20%	
				1009.44	
				L/S- \$1,000/3 DAYS	