

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011533/UUY3N2**Date:** 19/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00138142102		
Claimant Vehicle No :	XE5011A	Insured Vehicle No :	XD9829L		
Date of Loss:	08/11/2021	Nature of Claim:	TP	Claim No:	SNM21D206481/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE5011A		
Make & Model:	MITSUBISHI FUSO, 10.7 D FV70HJD2VDEA (M)	Engine No:	470912C0460317
Reg. Date:	22/07/2019 (Man. Year: 2019)	Chassis No:	FV70HJA00137
Colour:	White	Odometer:	169330 km
Engine Capacity:	10677 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80R22.5	Rear Tyre Size:	295/80R22.5(D/D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/66/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,123.00	0.00	4,123.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,100.00	1,880.00	63.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,103.00	1,100.00	6,003.00	84.51
+ GST 7.00/7.00% (\$\$)	497.21	77.00	420.21	84.51
Nett Amount (\$\$)	7,600.21	1,177.00	6,423.21	84.51

INSPECTION

Date of Assignment:	11/11/2021		
Date Inspected:	12/11/2021	Inspected At:	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2021)	
Parts:	N/A	MITSUBISHI FUSO 10.7 D FV70HJD2VDEA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE5011A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TIPPER TAIL GATE	Repair	2,535.00 FS	*- FS
2	2		*SET REAR TIPPER GATE HINGE & PIN-LH/RH	Repair	1,248.00 FS	*- FS
3	2		*REAR TIPPER LOCK HOOK-LH/RH	Repair	160.00 FS	*- FS
4	2		*REAR TIPPER LOCK HOOK SHAFT-LH/RH	Repair	180.00 FS	*- FS
Total Parts (S\$)					4,123.00	0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO CUT & WELD & JACK REAR TIPPER TAIL GATE HINGE,PIN	New	1,100.00	600.00
2	TO SPRAY & PAINTING REAR TIPPER DOOR & ALL ABOVE PARTS	New	1,200.00	500.00
3	TO RUST PROOFING AT ACCIDENT AREA	New	680.00	0.00
Gross Labour Cost (\$)			2,980.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >