

08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT121011533/443

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

XE5011A

at Workshop m/s

Mehlan

Hann

of

Insured:

XD982RL

Policy No.

DMCVSNW00138142102

Claims No.

SNM21D206481/C02

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$150k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

1.5-1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

943d

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

XE5011A

Yr Regn:

22/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mif Zuso FV70 c.c 10677

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

169330

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FV70 HJA 00137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/S / S/Rim / STD A/Rim or

Tyre Size:

F:

295 / 80 R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firenza

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6 6/6 mm

L/Bal.

6

mm

L/Bal.

6/6 6/6 mm

D.O.A.

8/1/14

D.O.I.

12/1/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 20k.

Confirmed 9/12 \$1100 with Schui

2 repair days

(RED \$6003; 85%)

Date/Time, File Pass to?



Preli. Report

1) 17/11 TYPIST



Final Report

Date/Time, File Return to?

2)

Report Format: TP

Comp Sum / I.B.I: (\$ 1100)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

)

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

MAH LIAN MOTOR VEHICLE REPAIRER

No 38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO 201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

TEL: - FAX: -
 ATTN: Motor Claim Department

Your Ref No: FUYUAN RESOURCES PL
 Claim Type: Third Party
 Accident Date: 08/11/2021
 TP Veh Reg No: XD9829L

Estimate No: ES1700918
 Date: 08 Nov 2021
 Policy No: DMCVSNW00084272102
 Veh Reg No: XE5011A
 Make/Model: MITSUBISHI FUSO
 FV70HJD2VDEA
 Chassis No: FV70HJA00137
 Engine No: 470912C0460317
 Reg. Date: 22/07/2019

Estimate Repair Cost to Vehicle No :XE5011A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 Rear Tipper Tail Gate	2,535.00	1 PC	2,535.00 X	
2 Rear Tipper Gate Hinge & Pin - LH/RH	624.00	2 SET	1,248.00 X	
3 Rear Tipper Lock Hook - LH/RH	80.00	2 PC	160.00 X	
4 Rear Tipper Lock Hook Shaft - LH/RH	90.00	2 PC	180.00 X	
			4,123.00	4,123.00
Labour				
5 Labour to cut & weld & jack rear tipper tail gate ,hinge ,pin .	1,100.00	1 JOB	1,100.00 600	
6 To spray & painting rear tipper door & all above parts .	1,200.00	1 JOB	1,200.00 500	
7 To rust proofing at accident area .	680.00	1 JOB	680.00 X	
			2,980.00	2,980.00
Total				S\$ 7,103.00
			Add GST @ 7%	497.21
			Total Amount Payable	<u>S\$ 7,600.21</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED AND CENTS TWENTY ONE ONLY

not Antoned
 2 days
 12/11/21
 P/PB 1100
 2 days

For MAH LIAN MOTOR VEHICLE
 REPAIRER

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: