

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011534/EQY3N2**Date:** 25/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00107812101

**Claimant Vehicle
No :** GBD3616J**Insured Vehicle
No :** GBJ8674B

Date of Loss: 05/11/2021

Nature of Claim: TP

Claim
No: SNM21D206396/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBD3616J**Make & Model: HYUNDAI H-1 STAREX, 2.5 D CRDi AT ABS A/BAG
6DR (A)

Engine No: D4CBE592371

Reg. Date: 30/09/2014 (Man. Year: 2014)

Chassis No: KMFWBX7KMEU681162

Colour: White

Odometer: 132954 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R16C

Rear Tyre Size: 215/70 R16C

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,941.20	1,650.64	290.56	14.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	750.00	510.00	40.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,201.20	2,400.64	800.56	25.01
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	3,201.20	1,900.00	1,301.20	40.65
+ GST 7.00/7.00% (S\$)	224.08	133.00	91.08	40.65
Nett Amount (S\$)	3,425.28	2,033.00	1,392.28	40.65

INSPECTION

Date of Assignment: 11/11/2021

Date Inspected: 08/12/2021 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd
(Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Apr 2022)	
Parts:	N/A HYUNDAI H-1 STAREX 2.5 D CRDi AT ABS A/BAG 6DR (A) (Model not available in database)	
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for GBD3616J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Dented	1,489.70 FL	*1,489.70 FL
2	1		*FRT DOOR LOWER GARNISH RH	Not Necessary	250.40 FL	*- FL
3	1		*FRT DOOR OUTER HANDLE RH	Broken	62.80 FL	*62.80 FL
4	1		*FRT DOOR WEATHERSTRIP RH	Not Necessary	112.80 FL	*- FL
5	1		*FRT SIDE MIRROR ASSY RH	Cut	510.80 FL	*510.80 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	2,426.50 2,063.30
					- List Item Discount on L Items 20.00/20.00% (\$\$)	485.30 412.66
					Total Parts (\$\$)	1,941.20 1,650.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD,REMOVE & REPLACE ABOVE PARTS	New	400.00	200.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	500.00	250.00
3	TO REMOVE & REFIX FRT DOOR GLASS	New	60.00	50.00
4	TO REDRAW COMPANY LOGO	New	300.00	250.00
Gross Labour Cost (\$\$)			1,260.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >