

(09/11/13) wef
ASS. REC. BY: PASAL

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
at Workshop m/s _____
of _____


Insured: QBC
Policy No. _____

Claims No. _____
Sum Insured: _____ Excess: _____

(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SG 6121H Yr Regn: 2019 / APR
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 C.C. 10518

Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: 180969 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WMAA95Z2XKFO08960

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: - D/P

BS / DUN / EXNOVA / GP / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or D/P

Front R mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. 23/10/21 D.O.I. 02/11/21

Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to? : Prell. Report

1) : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

) _____ S + RS, _____ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$ _____)

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 02/11/2021

User ID : JeongCH

Section A - Accident Details

Registration Number	SG6121H
Case Reference Number	BUS/10/21/5054
Registration Date	4/2/2019
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95 EU6
Name of Driver	Hameed Sultan Bin Osman Ally
Type of Accident	Head To Side
Accident Date and Time	10/23/2021 4:22 PM
Accident Reported Date and Time	11/1/2021 11:10 AM
Insurance Surveyor Required?	No
Surveyed by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG6121H-LEFT CENTER BODY SCRATCHED SDY818D (TP) INSURED WITH QBE
Prepared Date and Time	11/2/2021 10:37 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$602.00	\$0.00
Total Spare Part Cost	\$225.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,622.00	\$0.00
Amount Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	<i>2 days</i>
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	02/11/2021 10:43 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/11/2021
User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	530
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	432
Total Spray Painting & Panel Beating	\$602.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
013917			TRIM,WHEELARCH:FOR MAN A95 EURO 6	1.00	\$250.00	10.00	\$225.00	Replace	cm
Total					\$250.00		\$225.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068

2 days

P/P

02/11/21 @ 1510

Resurvey before paint