

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21011545/KPS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070176901
Claimant Vehicle No :	SHD5916J	Insured Vehicle No :	SMX516Z
Date of Loss:	08/11/2021	Nature of Claim:	TP
		Claim No:	3635020027SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5916J	Engine No:	2ZR2B62708
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203075411
Reg. Date:	01/11/2018 (Man. Year: 2018)	Odometer:	317466 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,269.72	814.17	2,455.55	75.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,490.00	480.00	5,010.00	91.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,759.72	1,294.17	7,465.55	85.23
+ GST 7.00/7.00% (S\$)	613.18	90.59	522.59	85.23
Nett Amount (S\$)	9,372.90	1,384.76	7,988.14	85.23
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$96.30/day) (S\$)		288.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,831.11		
Global Sum Settlement (S\$)		1,800.00		

INSPECTION

Date of Assignment:	10/11/2021		
Date Inspected:	10/11/2021	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Dented / Mtg Cracked	442.60 FL	*442.60 FL
2	1		*COVER ,REAR BUMPER LOWER	Serviceable	15.40 FL	*- FL
3	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	123.70 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
5	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
6	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
7	1		*LENS AND BODY ,REAR LAMP ,RH	Serviceable	502.00 FL	*- FL
8	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	443.30 FL	*- FL
9	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
10	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*50.00 FS
11	1		*REAR TAIL LAMP CLIP	Not Necessary	65.00 FS	*- FS
12	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
13	1		*CLIP (FOR REAR DOOR TRIM BOARD)	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,041.30	1,068.90
- List Item Discount on L Items 25.00/25.00% (\$)	771.58	254.73
Total Parts (\$)	3,269.72	814.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	280.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,500.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,490.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >