

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21011546/AVCE2

**Date:** 21/01/2022

### REFERENCE

Insured/Claimant:	NG KOK WAH	Policy No:	1800061529		
Date of Loss:	05/11/2021	Nature of Claim:	OD	Claim No:	1384995455SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFV2818H		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK060539
Reg. Date:	02/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF40JA159718
Colour:	Grey	Odometer:	77739 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,112.00	3,087.76	10,024.24	76.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,642.00	3,052.00	2,590.00	45.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,754.00</b>	<b>6,139.76</b>	<b>12,614.24</b>	<b>67.26</b>
<b>- Excess (S\$)</b>	<b>550.00</b>	<b>550.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>18,204.00</b>	<b>5,589.76</b>	<b>12,614.24</b>	<b>69.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,274.28</b>	<b>391.28</b>	<b>883.00</b>	<b>69.29</b>
<b>Nett Amount (S\$)</b>	<b>19,478.28</b>	<b>5,981.04</b>	<b>13,497.24</b>	<b>69.29</b>

### INSPECTION

Date of Assignment:	12/11/2021		
Date Inspected:	10/11/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIPS	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	210.00 FS	*- FS
5	1		*FRONT AIR GUIDE - LH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT AIR GUIDE GRILLE - LH	Not Necessary	135.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
8	1		*FRONT FENDER - LH	Dented	767.00 FS	*613.20 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	202.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	72.00 FS	*- FS
11	1		*FRONT FENDER BRAKET - LH	Not Necessary	35.00 FS	*- FS
12	1		*FRONT FENDER BRACKET SUPPORT - LH	Not Necessary	118.00 FS	*- FS
13	1		*FRONT FENDER BRAKET DEFORMATION ELEMNT - LH	Not Necessary	49.00 FS	*- FS
14	1		*FRONT FENDER REAR BRAKET - LH	Not Necessary	32.00 FS	*- FS
15	1		*FRONT FENDER WHEEL HOUSING - LH	Not Necessary	240.00 FS	*- FS
16	1		*FRONT FENDER WHEEL HOUSING ATTACHEMENT PART (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*FRONT WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
18	1		*FRONT SPOILER - LH	Not Necessary	35.00 FS	*- FS
19	1		*FRONT FENDER TRIM PROTECTION - LH	Necessary	31.00 FS	*24.64 FS
20	1		*FRONT FENDER UPPER TRIM PROTECTION - LH	Necessary	23.00 FS	*17.92 FS
21	1		*FRONT LED HEADLIGHT - LH	Not Necessary	7,693.00 FS	*- FS
22	1		*FRONT HEADLIGHT WASHER - LH	Not Necessary	210.00 FS	*- FS
23	1		*FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
24	1		*FRONT TYRE RIM	Cut	980.00 FS	*980.00 FS
25	1		*SUNDRIES	Necessary	250.00 FS	*22.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,112.00 3,087.76

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE / POST WHEEL ALIGNMENT	New	520.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>5,642.00</b>	<b>3,052.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >