

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011547/UGA3Q2**Date:** 21/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210080982
Claimant Vehicle No :	YQ1224D	Insured Vehicle No :	GBB1458Y
Date of Loss:	09/11/2021	Nature of Claim:	TP
		Claim No:	0993166890SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ1224D	Engine No:	4P10D75177
Make & Model:	mitsubishi canter, 3.0 D FEB21ER4SDEN (M)	Chassis No:	FEB21EA30179
Reg. Date:	16/07/2019 (Man. Year: 2019)	Odometer:	146718 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15 (D)
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6/6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,550.00	7,283.94	5,266.06	41.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,790.00	1,220.00	40.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,560.00	9,073.94	6,486.06	41.68
Approved Total (Overridden) (S\$)		7,250.00		
Nett Amount (S\$)	15,560.00	7,250.00	8,310.00	53.41
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,817.45		

INSPECTION

Date of Assignment:	12/11/2021	
Date Inspected:	12/11/2021 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	1,133.40 F	*1,133.40 FL
2	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
3	1		*FRONT GRILLE	Cracked	1,105.70 F	*685.10 FL
4	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
5	1		*FRONT GRILLE MITSUBISHI LOGO GRILLE	Necessary	187.00 F	*90.00 FL
6	1		*FRONT CANTER EMBLEM	Necessary	86.00 F	*75.70 FL
7	1		*FRONT DASHBOARD (FUEL BOX) COVER (LOWER N/S)	Deformed / Cracked	579.00 F	*579.00 FL
8	1		*FRONT LH BUMPER SIDE	Distorted	375.00 F	*304.15 FL
9	1		*SET FRONT LH BUMPER SIDE CLIPS	Not Necessary	45.00 FS	*- FS
10	1		*FRONT LH DOOR	Dented / Cracked	2,001.50 F	*1,800.67 FL
11	1		*FRONT LH DOOR HINGES	Lower Dented	230.00 F	*115.00 FL
12	1		*FRONT WINDSCREEN RUBBER	Cut	171.00 F	*171.00 FL
13	1		*FRONT LH DOOR DRAUGHT WEATHERSTRIP	Necessary	408.40 F	*282.50 FL
14	1		*FRONT LH DOOR INNER TRIM BOARDS	Deformed / Torn	593.90 F	*593.90 FL
15	1		*SET FRONT LH DOOR INNER TRIM BOARDS	Necessary	45.00 F	*45.00 FL
16	1		*FRONT LH DOOR LOCK	Dented / Shorted	367.20 F	*367.20 FL
17	1		*FRONT LH STEP PANEL GARNISH	Cracked	647.40 F	*647.40 FL
18	1		*SET FRONT DOOR CORPORATE STICKER N/S	Necessary	613.20 FS	*200.00 FS
19	1		*FRONT LH CORNER PANEL	Cracked	474.60 F	*408.20 FL
20	1		*FRONT LH SIDE MIRROR ARM	Bent	513.80 F	*513.80 FL
21	1		*FRONT LH SIDE MIRROR SQUARE	Not Necessary	107.70 F	*- FL
22	1		*FRONT LH SIDE MIRROR ROUND	Broken	110.50 F	*110.50 FL
23	1		*FRONT LH HEAD LAMP	Broken	1,712.80 F	*856.40 FL
24	1		*SET FRONT LH HEAD LAMP CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*FRONT LH SDE LAMPS	Broken	365.10 F	*180.20 FL
26	1		*FRONT LH SIGNAL LAMP	Broken	324.30 F	*263.63 FL
27	1		*SET FRONT LH SIGNAL LAMP CLIPS	Not Necessary	20.00 FS	*- FS
28	1		*FRONT LH WIPER TANK	Deformed	222.50 F	*222.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,550.00	9,645.25
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,361.31
Total Parts (\$\$)	12,550.00	7,283.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00
2	TO REMOVE,REPLACE AND TRANSFER DOOR PANEL ,FITTING AND MECHANISMS	New	80.00	60.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	800.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,000.00	850.00
5	REMOVE & REINSTALL DASHBOARD METER INSTRUMENTS ,DISCONNECT WIRING & ETCS	New	450.00	0.00
6	REMOVE & REINSTALL GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST	New	120.00	0.00
7	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
Gross Labour Cost (\$\$)			3,010.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >