

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011550/AVCN2**Date:** 23/03/2022**REFERENCE**

Insured/Claimant:	TAN QIU HAO, ASHLEY	Policy No:	7210054279	
Date of Loss:	08/11/2021	Nature of Claim:	OD	Claim No: 9474942379SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDQ3339S		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC37976
Reg. Date:	31/05/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF33M1105583
Colour:	White	Odometer:	6073 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,556.00	15,117.44	12,438.56	45.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,144.00	8,297.00	6,847.00	45.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	42,700.00	23,414.44	19,285.56	45.17
+ GST 7.00/7.00% (S\$)	2,989.00	1,639.01	1,349.99	45.17
Nett Amount (S\$)	45,689.00	25,053.45	20,635.55	45.17

INSPECTION

Date of Assignment:	12/11/2021		
Date Inspected:	10/11/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,335.00 FS	*1,068.00 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-RH	Not Necessary	59.00 FS	*- FS
5	1		*FRONT BUMPER TRIM-MANHATTAN GREY	Cut	356.00 FS	*284.40 FS
6	1		*FRONT BUMPER LOWER GRILLE-CENTER	Cut	217.00 FS	*173.20 FS
7	2		*FRONT PARKING AID SENSOR SUPPORT-LH/RH INNER	Not Necessary	50.00 FS	*- FS
8	1		*FRONT BUMPER LOWER GRILLE CAP	Not Necessary	51.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
10	1		*FRONT BUMPER LOWER SPOILER	Cracked	763.00 FS	*610.00 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	153.00 FS	*- FS
12	1		*FRONT BUMPER TRIM-RH MANHATTAN GREY	Not Necessary	164.00 FS	*- FS
13	1		*FRONT PARKING AID SENSOR BRACKET-RH	Not Necessary	25.00 FS	*- FS
14	1		*RADIATOR GRILLE	Cracked	1,928.00 FS	*1,542.40 FS
15	1		*RADIATOR STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
16	1		*FRONT 360 DEGREE CAMERA CAP	Not Necessary	56.00 FS	*- FS
17	1		*FRONT 360 DEGREE CAMERA BRACKET	Not Necessary	41.00 FS	*- FS
18	1		*RADIATOR TOP COVER	Cracked	244.00 FS	*194.80 FS
19	1		*FRONT 360 DEGREE CAMERA	Not Necessary	1,141.00 FS	*- FS
20	1		*FRONT BUMPER FOAM FILLER PIECES	Not Necessary	102.00 FS	*- FS
21	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	916.00 FS	*732.40 FS
22	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	39.00 FS	*- FS
23	1		*FRONT BUMPER TOP COVER	Cracked	123.00 FS	*98.00 FS
24	2		*CAUTION STICKER	Necessary	28.00 FS	*16.56 FS
25	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
26	1		*FRONT PARKING AID SENSOR (3 Pcs)	Not Necessary	0.00 FS	*- FS
27	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
28	1		*FRONT BUMPER WIRING SET	Not Necessary	572.00 FS	*- FS
29	1		*SIGNAL HORN LOW TONE-RH	Not Necessary	130.00 FS	*- FS
30	1		*SIGNAL HORN BRACKET-RH	Not Necessary	22.00 FS	*- FS
31	1		*FRONT FENDER-RH	Repair	1,286.00 FS	*- FS
32	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
33	1		*FRONT FENDER BRACE-RH	Not Necessary	88.00 FS	*- FS
34	1		*FRONT FENDER BRACKET-RH	Not Necessary	32.00 FS	*- FS
35	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	33.00 FS	*- FS
36	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	0.00 FS	*- FS
37	1		*FRONT WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
38	1		*FRONT WHEEL HOUSING COVER-RH	Not Necessary	16.00 FS	*- FS
39	1		*BONNET	Dented	3,508.00 FS	*2,806.40 FS
40	2		*BONNET HINGES-LH/RH	Not Necessary	146.00 FS	*- FS
41	1		*BONNET ATTACHMENT PARTS	Not Necessary	296.00 FS	*- FS
42	1		*BONNET STRIKER-RH	Not Necessary	110.00 FS	*- FS
43	1		*BONNET SOUND ABSORBER	Not Necessary	219.00 FS	*- FS
44	1		*BONNET IMPACT PROTECTION-CENTER	Necessary	28.00 FS	*21.84 FS
45	1		*FRONT FENDER TOP COVER-RH	Not Necessary	41.00 FS	*- FS
46	1		*PLENUM CHAMBER COVER	Not Necessary	129.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE-CENTER	Not Necessary	58.00 FS	*- FS
48	2		*BONNET LID LOCK MICROSWITCH-RH	Not Necessary	214.00 FS	*- FS
49	1		*BONNET LATCH	Not Necessary	58.00 FS	*- FS
50	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
51	1		*BONNET BOWDEN CABLE CAP	Not Necessary	10.00 FS	*- FS
52	1		*HEADLIGHT MOUNTING-RH	Cracked	118.00 FS	*94.40 FS
53	1		*LED HEADLIGHT-RH	Cracked	5,589.00 FS	*4,471.20 FS
54	1		*HEADLIGHT ELECTRONIC POWER MODULE-RH	Not Necessary	758.00 FS	*- FS
55	1		*HEADLIGHT HEAT SINK-RH	Not Necessary	781.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*LIFT CYLINDER-RH	Not Necessary	210.00 FS	*- FS
57	1		*LIFT CYLINDER HOSE-RH	Cut	80.00 FS	*63.44 FS
58	1		*LOCK CARREIER	Cracked	1,272.00 FS	*1,017.60 FS
59	1		*RADIATOR COOLANT (6 Pcs)	Necessary	266.00 FS	*212.64 FS
60	1		*RADIATOR AIR GUIDE-RH	Deformed	38.00 FS	*29.76 FS
61	2		*RADIATOR AIR GUIDE-UPPER/LOWER	Torn (1 Pc only)	84.00 FS	*33.04 FS
62	1		*OUTSIDE TEMPERATURE SENSOR HOLDER	Not Necessary	7.00 FS	*- FS
63	2		*FRONT WHEEL ARCH COVER-LH/RH	Necessary	1,072.00 FS	*857.60 FS
64	1		*FRONT WINDOW SLOT SEAL-RH	Not Necessary	224.00 FS	*- FS
65	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
66	1		*SUNDRIES	Necessary	400.00 FS	*31.68 FS
67	1		*COOLANT COMPRESSOR OIL-250ML (Supplementary)	Necessary	622.00 FS	*497.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	27,556.00	15,117.44
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO RENEW AND RENEW AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.TO RENEW ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	2,000.00	2,000.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY BOTH FRONT DOOR	New	280.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER.BONNET,RHS FRONT FENDERS AND RHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
6	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER,BONNET HINGES,RHS FRONT FENDER,RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS	New	6,000.00	2,875.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			15,144.00	8,297.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >