

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011553/KVY3N2**Date:** 03/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00047342101

**Claimant Vehicle No :** SLU868K **Insured Vehicle No :** SLF527Z

Date of Loss: 07/11/2021 Nature of Claim: TP Claim No: SNM21D206408/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLU868K**

Make & Model: BMW 320I, 2.0 (A) Engine No: B557I317N46B20BD

Reg. Date: 25/06/2009 (Man. Year: 2008) Chassis No: WBAWA52020P300662

Colour: White Odometer: 188001 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,248.78	4,742.28	2,506.50	34.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,515.00	880.00	1,635.00	65.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,763.78</b>	<b>5,622.28</b>	<b>4,141.50</b>	<b>42.42</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>9,763.78</b>	<b>4,500.00</b>	<b>5,263.78</b>	<b>53.91</b>

**INSPECTION**

Date of Assignment: 12/11/2021

Date Inspected: 16/11/2021 Inspected At: Trust Autoworks - Ang Mo Kio (HQ)  
Blk 5035, #01-345 Ang Mo Kio Industrial Pk 2  
Singapore 569538

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
<b>Parts:</b>	143	BMW 320I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU868K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S TAIL-LAMP-LED	Shorted	850.00 FL	*784.00 FL
2	1		*REAR END PANEL	Repair	781.00 FL	*- FL
3	1		*REAR END PANEL INNER GARNISH	Serviceable	137.00 FL	*- FL
4	1		*REAR BUMPER	Cracked/Buckled	1,550.00 FL	*1,435.00 FL
5	1		*REAR BUMPER LOWER GARNISH	Dented	855.00 FL	*755.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	681.00 FL	*- FL
7	1		*REAR BUMPER INNER TOP BRACKET	Cracked	175.20 FL	*175.20 FL
8	1		*REAR N/S BUMPER SIDE BRACKET	Distorted	195.00 FL	*195.00 FL
9	2		*REAR REVERSE SENSOR	Shorted	570.00 FL	*450.00 FL
10	1		*REAR EXHAUST SILENCER	Bent	1,875.00 FL	*1,150.00 FL
11	1		*FRONT DRIVER SEAT HEAD REST COLLISION SENSOR	Dented	385.00 FL	*325.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,054.20</b>	<b>5,269.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	805.42	526.92
<b>Total Parts (\$\$)</b>	<b>7,248.78</b>	<b>4,742.28</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	800.00	400.00
2	TO PUTTY AND SPRAY PAINT	New	800.00	400.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	0.00
5	REMOVE/RENEW REAR EXHAUST SILENCER	New	180.00	60.00
6	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	0.00
7	DIAGNOSTIC CHECK ON AIR BAG SYSTEM AND TO RESET TO FACTORY SPECIFICATION	New	450.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,515.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >