

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121011556/AQF3N2**Date:** 09/02/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKR9506Z**Insured Vehicle No :** GBL1803G

Date of Loss: 10/11/2021

Nature of Claim:

TP

Claim No: CDMCG21002175

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKR9506Z**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P520265622

Reg. Date: 18/03/2015 (Man. Year: 2015)

Chassis No: JM6BM42A8G0302549

Colour: Red

Odometer: 123312 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,399.10	4,334.72	4,064.38	48.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,260.00	590.00	31.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,249.10	5,594.72	4,654.38	45.41
Approved Total (Overridden) (S\$)		4,450.00		
Nett Amount (S\$)	10,249.10	4,450.00	5,799.10	56.58

INSPECTION

Date of Assignment: 12/11/2021

Date Inspected: 12/11/2021 Inspected At:

Automobile Hub Enterprise

1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @

KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2022)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKR9506Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	958.10 F	*958.10 FL
2	1		*FRONT BUMPER SIDE HOLDER LH	Necessary	28.20 F	*28.20 FL
3	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	351.30 F	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	87.00 F	*- FL
5	1		*FRONT BUMPER SIGNAL LAMP LH	Not Necessary	165.20 F	*- FL
6	1		*HEADLAMP LH	Cracked	2,357.30 F	*2,357.30 FL
7	1		*FRONT LH FENDER	Dented	392.90 F	*392.90 FL
8	1		*FRONT LH FENDER INNER SHIELD	Deformed	129.30 F	*129.30 FL
9	1		*FRONT LH LOWER ARM	Bent	484.90 F	*484.90 FL
10	1		*FRONT LH SHOCK ABSORBER	Not Necessary	381.10 F	*- FL
11	1		*FRONT LH KNUCKLE ARM	Not Necessary	486.10 F	*- FL
12	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	367.70 F	*367.70 FL
13	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT BUMPER LOWER SPOILER	Repair	1,000.00 FS	*- FS
15	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
16	1		*FRONT LH WHEEL RIM	Cut	850.00 FS	*500.00 FS
17	1		*FRONT LH TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,399.10	5,278.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	943.68
Total Parts (\$\$)	8,399.10	4,334.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	500.00
2	SPRAY PAINTING	New	600.00	500.00
3	WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
5	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	150.00
Gross Labour Cost (\$)			1,850.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >