

Automobile Hub

SKR9506Z 2015 March.

Mazda 3 1496cc

TP Ergo.

XiaoChen.

JM6BM42A860302549.

Front Bumper torn 958.10 ✓

Front Bumper Clips. New 30(SN) ✓

Front Bumper Side Holder LH. New 28.20 ✓

Front Bumper Fog Lamp LH. } NP 351.30 x

Front Bumper Fog Lamp Cover LH } New 87 x

Front Bumper Signal Lamp LH. } 165.20 x

Front Bumper lower Spoiler ^{Plastic} 1000(SN) x

Headlamp LH. cracked 2357.30 ✓

Front LH Fender Dented 392.90 ✓

Front LH Fender Inner Shield. Deformed 129.30 ✓

Front LH Fender Inner Shield Clips. New 30(SN) ✓

SKR9506Z.

Front LH Wheel Rim. ^{WT} ~~850(SN)~~ 500(SN)

Front LH Tyre. ^{NP} ~~300(SN)~~ X

Front LH Lower Arm. ^{Bent} 484.90 ✓

Front LH Shock Absorber ^{NP} 381.10 X

Front LH Knuckle Arm. ^{NP} 486.10 X

Front LH Wheel Hub c/w ^{Damaged} Bearings. 367.10. ✓

4718.40

S.N: 560

3774.72

Panel Beating
Spray Painting.

1260

Wiring.

To perform wheel alignment.

To dismantle front undercarriage

~~700~~ 500

~~600~~ 500

~~50~~ 30

~~150~~ 80

~~350~~ 150.

total: 5594.72

L/S: 4450

05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: