

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S1M03J6Z Date: 29th Nov 2021

Our Ref: CS3/ASM21010262/Vty3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PC 4843C INSURED VEHICLE: SHC 8677J

ACCIDENT DATE: 01/10/2021

We thank you for your instruction on 12/11/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PC 4843C from M/s Precise Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicle PC 4843C and SHC 8677J.
- c) Colour damaged vehicle photographs of PC 4843C.

Pre-Repair Inspection Date: 05/10/2021 at M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : PC 4843C

Make & Model : Toyota Hiace DX 3.0 A

Year of Registration : 2016

Chassis Number : KDH2010194981

Engine Capacity : 2982 cc

- We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.