

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR21011558/Euf3e2	
	60 WOODLANDS I E4SINGAPORE 75		Date:	19/11/2021		
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 4172A	Veh. Inspected	l	FBF 6891A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/10/21/2059	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		12/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA T135	c.c		135	
	Engine No.	HIDDEN	Year of Reg.		2011	
	Chassis No.	5YP303486	Colour		BLACK	
	Odometer	2015 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70/90-17	DIABLO		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/90-17	DIABLO		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5.	5. General Information					
	Accident Date	23/10/2021	Inspect Date /	Time	12/11/2021 ( 03:59 PM )	
	Survey held at HUA CHIN (2000) TRADING MOTOR SVC CENTRE					
	50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500-\$1,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		2 Worki	ing Days	

Report Ref No. CS3/SMR21011558/Euf3e2

Inspected By

CHEN TSUE YEE

**Automotive Assessor** 

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser