

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011561/KGS3Q2**Date:** 15/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700054576-04
<b>Claimant Vehicle No :</b>	SNC6263L	<b>Insured Vehicle No :</b>	GBG6362E
Date of Loss:	11/11/2021	Nature of Claim:	TP
		Claim No:	7252500802SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNC6263L</b>	Engine No:	1NZR800356
Make & Model:	TOYOTA SIENNA, 1.5 (A)	Chassis No:	NHP1707178098
Reg. Date:	08/01/2021 (Man. Year: 2019)	Odometer:	55936 km
Colour:	Metallic Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	INTERTRAC 9 mm	Rear Left Side:	INTERTRAC 9 mm
Front Right Side:	INTERTRAC 9 mm	Rear Right Side:	INTERTRAC 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,271.75	5,008.05	3,263.70	39.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,540.00	890.00	36.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,701.75</b>	<b>6,548.05</b>	<b>4,153.70</b>	<b>38.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,250.00</b>		
<b>(S\$)</b>	10,701.75	5,250.00	5,451.75	50.94
<b>+ GST 7.00/7.00% (S\$)</b>	749.12	367.50	381.62	50.94
<b>Nett Amount (S\$)</b>	<b>11,450.87</b>	<b>5,617.50</b>	<b>5,833.37</b>	<b>50.94</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>(S\$)</b>		5,977.50		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>2,988.75</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,990.75</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,990.00</b>		

INSPECTION

Date of Assignment:	12/11/2021		
Date Inspected:	12/11/2021	Inspected At:	Optima Werkz Pte Ltd (HQ) 6 Kung Chong Road Singapore 159143
Estimated Period of Repair:	6.0 days		

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET HINGE LH	Repair	70.00 FL	*- FL
2	1		*FRONT BONNET HINGE RH	Repair	70.00 FL	*- FL
3	1		*FRONT HEADLAMP RH	Mtg Broken	1,029.00 FL	*1,029.00 FL
4	1		*FRONT BUMPER	Buckled	350.00 FL	*350.00 FL
5	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	55.00 FL	*55.00 FL
6	1		*FRONT BUMPER FOG LAMP GARNISH COVER RH	Cut	110.00 FL	*110.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	363.00 FL	*- FL
8	1		*FRONT BUMPER ABSORBER FOAM	Serviceable	95.00 FL	*- FL
9	1		*FRONT FENDER RH	Bent	579.00 FL	*579.00 FL
10	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	70.00 FL	*70.00 FL
11	1		*FRONT FENDER INNER SHIELD RH	Distorted	185.00 FL	*185.00 FL
12	1		*FRONT PILLAR QUARTER GARNISH COVER RH	Dented	130.00 FL	*130.00 FL
13	1		*FRONT SIDE MIRROR ASSY RH	Cracked	1,109.00 FL	*866.10 FL
14	1		*FRONT SIDE MIRROR COVER RH	Cracked	109.00 FL	*109.00 FL
15	1		*FRONT SIDE MIRROR GLASS RH	Broken	155.00 FL	*155.00 FL
16	1		*FRONT WHEEL RIM RH	Serviceable	395.00 FL	*- FL
17	1		*FRONT WHEEL RIM COVER RH	Missing	211.00 FL	*211.00 FL
18	1		*FRONT ABSORBER RH	Bent	468.00 FL	*417.00 FL
19	1		*FRONT KNUCKLE ARM RH	Bent	497.00 FL	*455.70 FL
20	1		*FRONT WHEEL BEARING RH	Necessary	158.00 FL	*158.00 FL
21	1		*FRONT CONTROL ARM RH	Distorted	895.00 FL	*497.00 FL
22	1		*FRONT DOOR RH	Dented / Warped	1,249.00 FL	*1,180.60 FL
23	1		*FRONT DOOR INNER TRIM BOARD RH	Serviceable	1,124.00 FL	*- FL
24	1		*FRONT DOOR UPPER HINGE RH	Repair	90.00 FL	*- FL
25	1		*FRONT DOOR LOWER HINGE RH	Repair	90.00 FL	*- FL
26	1		*FRONT DOOR CHECKER RH	Serviceable	185.00 FL	*- FL
27	1		*FRONT DOOR WINDOW REGULATOR RH	Serviceable	237.00 FL	*- FL
28	1		*FRONT DOOR WINDOW MOTOR RH	Serviceable	711.00 FL	*- FL
29	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
30	1		*FRONT BONNET INSULATOR CLIPS	Not Necessary	40.00 FS	*- FS
31	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
32	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FS	*40.00 FS
33	1		*FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,969.00</b>	<b>6,647.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,697.25	1,639.35
<b>Total Parts (\$)</b>	<b>8,271.75</b>	<b>5,008.05</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	900.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET ,FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH & ETC	New	900.00	680.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER ,RH FRONT KNUCKLE ARM RH ,FRONT WHEEL BEARING RH ,FRONT CONTROL ARM RH & ETC	New	250.00	200.00
4	TO WHEEL ALIGNMENT BALANCING	New	80.00	80.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
7	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>2,430.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >