

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011563/R1VF3E2

Date: 25/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMM2728Z

Insured Vehicle No : SMW6299R

Date of Loss: 05/11/2021

Nature of Claim: TP

Claim No: 3923979533SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM2728Z**

Make & Model: HONDA FREED HYBRID, 1.5 G (A)

Engine No: LEB5600262

Reg. Date: 24/07/2018 (Man. Year: 2018)

Chassis No: GB71067079

Colour: Blue

Odometer: 138460 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 6 mm

Rear Left Side: Sailun 6 mm

Front Right Side: Sailun 6 mm

Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/11/2021

Date Inspected: 23/11/2021

Inspected At:

Heng Yap Seng Auto Services (HQ)

160 Sin Ming Drive

#08-13 Sin Ming Autocity

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$84,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*REAR RH DOOR	Repair	0.00 F	*- F
3	1		*REAR RH DOOR RUBBER	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >