



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 8863H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOTS	BENT	804.30	804.30
1	REAR BOOTS LOCK	DENTED	256.10	256.10
1	REAR BOOTS RUBBER	DISTORTED / DENTED	101.30	101.30
1	SET REAR WINDSCREEN MOULDING (3 PCS)	NECESSARY	395.10	131.80
1	REAR WINDSCREEN GUM	NECESSARY	44.00	44.00
1	REAR BOOTS "H" EMBLEM	NOT NECESSARY	38.00	-
1	REAR BOOTS "VESEL" EMBLEM	NECESSARY	43.00	43.00
2	REAR TAILLAMP ASSY @\$425.00	SERVICEABLE	850.00	-
1	REAR BUMPER	BENT	850.00	762.70
6	REAR BUMPER CLIPS @\$5.50	NECESSARY	33.00	33.00
2	REAR BUMPER REFLECTOR @\$75.00	SERVICEABLE	150.00	-
1	SET REAR BUMPER REVERSE SENSOR (4 PCS PER SET)	SHORTED	301.70	301.70
1	REAR PANEL	TO REPAIR SEE LABOUR	411.90	-
	LESS 20% DISCOUNT		-	-495.58
			4,278.40	1,982.32
	<u>LABOUR</u>			
	TO KNOCK,WELD,REPAIR AND RENEW ALL AREAS AFFECTED BY THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR PANEL.		700.00	500.00
	TO SPRAY PAINT ALL AREAS AFFECTED BY THE ACCIDENT.		650.00	450.00
	TO REMOVE AND INSTALL REAR WINDSCREEN.		150.00	120.00
			1,500.00	1,070.00
	GRAND TOTAL		5,778.40	3,052.32



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	-----------------

Report Ref No. CS/AGI21011565/Ktf3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.