

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011566/VVY3N2**Date:** 10/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00134242000

Claimant Vehicle No : SMJ9809T**Insured Vehicle No :** SMV1787L

Date of Loss: 10/11/2021

Nature of Claim: TP

Claim No: SNM21D206486/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMJ9809T**

Make & Model: NISSAN NOTE, 1.2 (A)

Engine No: HR12003758K

Reg. Date: 26/03/2019 (Man. Year: 2019)

Chassis No: JN1TAAE12Z0982843

Colour: Red

Odometer: 6985 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15

Rear Tyre Size: 185/65R15

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,927.03	5,850.31	3,076.72	34.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	2,000.00	2,150.00	51.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,077.03	7,850.31	5,226.72	39.97
Approved Total (Overridden) (\$\$)		6,300.00		
(\$\$)	13,077.03	6,300.00	6,777.03	51.82
+ GST 7.00/7.00% (\$\$)	915.39	441.00	474.39	51.82
Nett Amount (\$\$)	13,992.42	6,741.00	7,251.42	51.82

INSPECTION

Date of Assignment: 12/11/2021

Date Inspected: 12/11/2021 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2021)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ9809T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	528.00 FL	*480.00 FL
2	2		*REAR BUMPER RETAINER	Necessary	121.00 FL	*121.00 FL
3	2		*REAR BUMPER REFLECTOR	Cracked	145.20 FL	*145.20 FL
4	2		*REAR BUMPER REFLECTOR COVER	Scratched	127.60 FL	*127.60 FL
5	1		*REAR BUMPER BRACKET	Necessary	106.26 FL	*106.26 FL
6	1		*REAR BUMPER DAMPER (2 Pcs)	Bent	212.52 FL	*158.45 FL
7	1		*REAR BUMPER SPONGE	Not Necessary	137.50 FL	*- FL
8	2		*TAILLAMP	Cracked	958.76 FL	*871.60 FL
9	2		*TAILLAMP BRACKET	Repair	121.00 FL	*- FL
10	1		*TAILGATE	Cut	1,423.40 FL	*1,018.20 FL
11	1		*TAILGATE EMBLEM-NOTE	Necessary	103.40 FL	*68.20 FL
12	1		*TAILGATE EMBLEM-LOGO	Necessary	71.39 FL	*71.39 FL
13	1		*TAILGATE OUTER GARNISH	Deformed	320.10 FL	*281.16 FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	126.50 FL	*108.46 FL
15	1		*TAILGATE LOCK	Distorted	170.50 FL	*170.50 FL
16	1		*TAILGATE LOCK STRIKER	Distorted	60.50 FL	*60.50 FL
17	1		*TAILGATE INNER TRIM BOARD	Cracked	217.80 FL	*217.80 FL
18	2		*TAILGATE HINGE	Repair	165.00 FL	*- FL
19	1		*TAILGATE GLASS MOULDING	Necessary	102.00 FL	*102.00 FL
20	1		*END PANEL	Bent	608.08 FL	*552.80 FL
21	1		*END PANEL TOP GARNISH	Deformed	119.30 FL	*119.30 FL
22	1		*KEYLESS SENSOR	Cracked	123.20 FL	*61.27 FL
23	2		*REAR FENDER INNER TRIM BOARD	Deformed	872.08 FL	*756.80 FL
24	1		*SPARE TYRE TOP BOARD	Cracked	477.07 FL	*263.70 FL
25	1		*SPARE TYRE COMPARTMENT	Repair	931.70 FL	*- FL
26	1		*EXHAUST SILENCER	Repair	646.80 FL	*- FL
27	2		*EXHAUST MOUNTING	Serviceable	38.00 FL	*- FL
28	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
29	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
30	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
31	1		*SET REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
32	1		*REAR NUMBER PLATE	Cracked	80.00 FS	*50.00 FS
33	1		*TAILGATE GLASS SEALANT	Necessary	150.00 FS	*70.00 FS
34	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
35	1		*FLOOR INSULATOR	Necessary	150.00 FS	*80.00 FS
36	2		*TAILLAMP PANEL	Dented	475.20 FL	*475.20 FL
37	1		*SPARE TYE COMPARTMENT SPONGE	Cut	523.93 FL	*288.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,933.79	7,175.39
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,006.76	1,325.08
Total Parts (\$\$)	8,927.03	5,850.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTNING SYSTEM	New	150.00	30.00
2	REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
3	REMOVE AND REFIT TRIMS AND GARNISH	New	150.00	30.00
4	REMOVE AND REPLACE EXHAUST SILENCER	New	150.00	0.00
5	REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
6	REMOVE AND REFIT TAILGATE ATTACHMENTS	New	150.00	30.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	800.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	800.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
10	REMOVE AND REFIT REAR SEAT TO FACILITATE REPAIR	New	250.00	130.00
Gross Labour Cost (\$\$)			4,150.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >