




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | |
|---|---|---|--|---|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: PAY DANIEL | | | Ref: CS3/ASM21011568/Gqy3e2 Date: 23/11/2021 Code: ASM | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | SHD 3247U | Veh. Inspected | GBG 1997G |
| | Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 |
| | Claim No. | S1M03LXN | Excess (\$) | 0.00 |
| | Assign From | PAY DANIEL | Assign Date | 12/11/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | NISSAN NV350 | c.c | 2488 |
| | Engine No. | HIDDEN | Year of Reg. | 2017 |
| | Chassis No. | JN1MC2E26Z0008209 | Colour | BROWN |
| | Odometer | 263602 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195 R15 | MICHELIN | 6 mm |
| | L/H Front Tyre | 195 R15 | MICHELIN | 6 mm |
| | R/H Rear Tyre | 195 R15 | MICHELIN | 6 mm |
| | L/H Rear Tyre | 195 R15 | MICHELIN | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. | | |  |
| 5. General Information | | | | |
| | Accident Date | 10/11/2021 | Inspect Date / Time | 16/11/2021 (10:40 AM) |
| | Survey held at | TAN ENG HUAT MOTOR BLK 6 DEFU LANE 10 #01-556 SINGAPORE 539187 | | |
| 5a. Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$500-\$1,000 | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |

Report Ref No. CS3/ASM21011568/Gqy3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.