

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011677/GQY3Q2**Date:** 06/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW0013092102
Claimant Vehicle No :	YQ4377B	Insured Vehicle No :	YP2314B
Date of Loss:	10/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206511/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ4377B	Engine No:	1GD8807419
Make & Model:	TOYOTA DYNA 1.5T, 3.0 (A)	Chassis No:	JHHAGV4610K001140
Reg. Date:	07/10/2021 (Man. Year: 2021)	Odometer:	3362 km
Colour:	Silver		
Engine Capacity:	2755 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	145/80 R13
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,149.07	4,725.27	18,423.80	79.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,110.00	1,310.00	2,800.00	68.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,259.07	6,035.27	21,223.80	77.86
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	27,259.07	4,800.00	22,459.07	82.39
+ GST 7.00/7.00% (\$\$)	1,908.13	336.00	1,572.13	82.39
Nett Amount (\$\$)	29,167.20	5,136.00	24,031.20	82.39

INSPECTION

Date of Assignment:	16/11/2021	
Date Inspected:	16/11/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 May 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ4377B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,514.00 FL	*1,370.00 FL
2	2		*TAIL GATE SIDE HANDLE	Bent (1 PCS ONLY)	358.00 FL	*179.00 FL
3	2		*TAIL GATE SIDE LOCK	Bent (1 PCS ONLY)	430.00 FL	*215.00 FL
4	1		*TAIL GATE LOWER SIDE RAILING RH	Bent	246.90 FL	*180.00 FL
5	2		*TAIL GATE LOWER SIDE RAILING MOUNTING	Cut	50.00 FL	*25.00 FL
6	4		*TAIL GATE HINGE	Not Necessary	496.40 FL	*- FL
7	1		*END PANEL	Repair	564.20 FL	*- FL
8	1		*REAR FLOOR PANEL	Not Necessary	1,854.00 FL	*- FL
9	2		*TAIL LAMP	Cracked (1 PCS ONLY)	709.80 FL	*208.50 FL
10	2		*TAIL LAMP BRACKET	Bent (1 PCS ONLY)	344.80 FL	*97.00 FL
11	2		*TAIL LAMP REFLECTOR	Cracked (1 PCS ONLY)	240.00 FL	*55.20 FL
12	1		*REAR CAR PLATE BRACKET	Bent	233.00 FL	*184.00 FL
13	2		*REAR CAR PLATE LAMP	Not Necessary	120.00 FL	*- FL
14	1		*SIDE GATE RH	Repair	1,898.60 FL	*- FL
15	1		*SIDE GATE BOTTOM PANEL RH	Not Necessary	752.40 FL	*- FL
16	1		*TAIL GATE ALUMINIUM PLATE	Bent	1,500.00 FS	*300.00 FS
17	1		*TAIL GATE COMPANY STICKER	Necessary	600.00 FS	*200.00 FS
18	1		*TAIL GATE STICKER (60KM/H)	Necessary	40.00 FS	*15.00 FS
19	1		*TAIL GATE STICKER (13 PAX)	Necessary	40.00 FS	*15.00 FS
20	1		*SIDE GATE COMPANY STICKER	Necessary	800.00 FS	*300.00 FS
21	2		*SIDE GATE ALUMINIUM PLATE	Buckled	3,600.00 FS	*700.00 FS
22	1		*SIDE GATE ALUMINIUM PLATE RIVET	Necessary	100.00 FS	*50.00 FS
23	1		*FLOOR PANEL ALUMINIUM PLATE	Buckled	2,500.00 FS	*600.00 FS
24	1		*FLOOR PANEL ALUMINIUM PLATE RIVET	Necessary	100.00 FS	*50.00 FS
25	1		*REAR CAR PLATE	Cut	60.00 FS	*10.00 FS
26	1		*REVERSE SENSOR (LONG)	Damaged	550.00 FS	*180.00 FS
27	2		*REVERSE SENSOR HOLDER	Bent	40.00 FS	*20.00 FS
28	1		*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*REAR CANOPY (LOCAL REPAIR)	Bent	3,500.00 FS	*250.00 FS
31	1		*REAR CANOPY	Bent	1,400.00 FS	*150.00 FS
32	2		*REAR BUMPER BRACKET	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,602.10	5,353.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,453.03	628.43
Total Parts (\$\$)	23,149.07	4,725.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,500.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	700.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	100.00	30.00
4	TO APPLY ANTI-RUST & TUFF-KOTE	New	200.00	40.00
5	REMOVE AND INSTALL TAIL GATE ,SIDE GATE	New	360.00	0.00
6	REMOVE AND RESEAL GATE RIVET SET	New	300.00	0.00
7	REMOVE & INSTALL REAR PARKING SENSOR AND WIRING HARNESS	New	100.00	40.00
8	REMOVE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	150.00	0.00
Gross Labour Cost (\$\$)			4,110.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >