

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21011576/KTF3N2**Date:** 02/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001627566
Claimant Vehicle No :	SLP2704M	Insured Vehicle No :	XD8614X
Date of Loss:	05/11/2021	Nature of Claim:	TP
		Claim No:	265126

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP2704M	Engine No:	HR12243939B
Make & Model:	NISSAN NOTE, 1.2 DIG-S CVT (A)	Chassis No:	JN1TBAE12Z0985062
Reg. Date:	30/05/2017 (Man. Year: 2017)	Odometer:	72815 km
Colour:	Metallic Silver		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,133.99	790.55	343.44	30.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,733.99	1,190.55	543.44	31.34
+ GST 7.00/7.00% (S\$)	121.38	83.34	38.04	31.34
Nett Amount (S\$)	1,855.37	1,273.89	581.48	31.34

INSPECTION

Date of Assignment:	12/11/2021	
Date Inspected:	22/11/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
Parts:	144	NISSAN NOTE 1.2 DIG-S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP2704M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Deep Cut	493.30 FN	*493.30 FN
2	1		*FRONT BUMPER REINFORCEMENT	Repair	381.60 FN	*- FN
3	1		*FRONT BUMPER RH TOW COVER	Dented	25.50 FN	*25.50 FN
4	6		*FRONT BUMPER CLIPS	Necessary	26.40 FN	*26.40 FN
5	1		*FRONT GRILLE	Cut	276.70 FN	*276.70 FN
6	4		*FRONT GRILLE CLIPS	Necessary	17.60 FN	*17.60 FN
7	1		*FRONT NUMBER PLATE	Scratched	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,256.10	874.50
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	122.11	83.95
Total Parts (\$\$)	1,133.99	790.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	300.00	200.00
2	PUTTY & RESPRAY PAINT	New	300.00	200.00
Gross Labour Cost (S\$)			600.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >