

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011581/EEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070067117
<b>Claimant Vehicle No :</b>	SHA242T	<b>Insured Vehicle No :</b>	SFU3398B
Date of Loss:	10/11/2021	Nature of Claim:	TP
		Claim No:	9975602357SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA242T</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDEU440390
Reg. Date:	12/11/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU079792
Colour:	Yellow	Odometer:	780584 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R15	Rear Tyre Size:	205/55 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,827.49	944.82	882.67	48.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	630.00	2,270.00	78.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,727.49</b>	<b>1,574.82</b>	<b>3,152.67</b>	<b>66.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		
<b>(S\$)</b>	4,727.49	1,250.00	3,477.49	73.56
<b>+ GST 7.00/7.00% (S\$)</b>	330.92	87.50	243.42	73.56
<b>Nett Amount (S\$)</b>	<b>5,058.41</b>	<b>1,337.50</b>	<b>3,720.91</b>	<b>73.56</b>
<b>+ Loss of Use (1.5 x S\$50.00/day) (S\$)</b>		75.00		
<b>+ Car Rental (1.5 x S\$107.43/day) (S\$)</b>		161.15		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,575.65</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,570.00</b>		

INSPECTION

Date of Assignment:	12/11/2021		
Date Inspected:	15/11/2021	Inspected At:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825
Estimated Period of Repair:	2.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Crushed	599.68 FL	*553.00 FL
2	1		*REAR BUMPER LOWER	Crushed	228.40 FL	*228.40 FL
3	1		*REAR BUMPER ENERGY ABSORBER	Necessary	99.62 FL	*99.62 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	484.40 FL	*- FL
5	1		*REAR LH BUMPER REINFORCEMENT BRACKET	Not Necessary	98.63 FL	*- FL
6	1		*REAR RH BUMPER REINFORCEMENT BRACKET	Not Necessary	98.63 FL	*- FL
7	1		*SET REAR BUMPER CLIPS	Necessary	75.00 FS	*30.00 FS
8	2		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
9	1		*REAR BUMPER LOWER CLIP	Necessary	65.00 FS	*10.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					2,149.36	1,121.02
- List Item Discount on L Items 20.00/20.00% (\$)					321.87	176.20
Total Parts (\$)					1,827.49	944.82

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	New	1,000.00	200.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	180.00	20.00
3	TO REMOVE AND REFIT OF NECESSARY ITEM TO FACILITATE REPAIR	New	300.00	0.00
4	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	270.00	30.00
5	TO REFIT REAR REVERSE SENSOR	New	150.00	30.00
6	TO RESPRAY REAR BUMPER	New	250.00	200.00
7	TO RESPRAY REAR BUMPER LOWER	New	250.00	120.00
8	TO RESPRAY REAR REVERSE SENSOR	New	250.00	30.00
9	TO RESPRAY REAR END PANEL OUTER	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,900.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >