

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011583/KEA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SGW2911D**Insured Vehicle No :** SMM9127L

Date of Loss: 09/11/2021

Nature of Claim: TP

Claim No: 7766365635SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGW2911D**

Make &amp; Model: BMW 520I, 2.0 LED NAV MSPT (A)

Engine No: 12505385B48B20A

Reg. Date: 29/10/2018 (Man. Year: 2018)

Chassis No: WBAJA12070BJ20786

Colour: Metallic Pearl White

Odometer: 62599 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 275/40 R18

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,601.22	5,304.22	4,297.00	44.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,550.00	820.00	34.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,971.22</b>	<b>6,854.22</b>	<b>5,117.00</b>	<b>42.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,450.00</b>		
<b>(S\$)</b>	11,971.22	5,450.00	6,521.22	54.47
<b>+ GST 7.00/7.00% (S\$)</b>	837.99	381.50	456.49	54.47
<b>Nett Amount (S\$)</b>	<b>12,809.21</b>	<b>5,831.50</b>	<b>6,977.71</b>	<b>54.47</b>
<b>+ Car Rental (6.0 x S\$160.00/day) (S\$)</b>		960.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>6,793.50</b>		

INSPECTION

Date of Assignment: 12/11/2021

Date Inspected: 12/11/2021 Inspected At:

Alan's United Auto Pte Ltd (HQ)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,574.64 FL	*1,574.64 FL
2	1		*BOOTLID BMW EMBLEM	Necessary	110.81 FL	*110.81 FL
3	1		*BOOTLID 520I EMBLEM	Necessary	87.48 FL	*87.48 FL
4	1		*BOOTLID WEATHERSTRIP	Serviceable	285.77 FL	*- FL
5	1		*BOOTLID LOCK	Repair	443.23 FL	*- FL
6	1		*BOOTLID LOCK POWER DRIVE	Serviceable	851.47 FL	*- FL
7	1		*BOOTLID INNER TRIM	Serviceable	443.23 FL	*- FL
8	1		*REAR BUMPER	Buckled	1,728.00 FL	*1,728.00 FL
9	4		*REVERSE SENSORS	Missing (1 PCS ONLY)	860.00 FL	*215.00 FL
10	1		*REAR BUMPER REFLECTOR (LH)	Serviceable	75.82 FL	*- FL
11	1		*REAR BUMPER REFLECTOR (RH)	Serviceable	75.82 FL	*- FL
12	1		*REAR BUMPER TOWING COVER	Serviceable	59.40 FL	*- FL
13	1		*REAR BUMPER LOWER GARNISH	Buckled	303.26 FL	*303.26 FL
14	1		*REAR BUMPER LOWER COVER	Serviceable	64.80 FL	*- FL
15	1		*REAR BUMPER LOWER INNER PART	Serviceable	75.60 FL	*- FL
16	1		*REAR BUMPER INNER PART	Cracked	108.00 FL	*108.00 FL
17	1		*R BUMPER LOW GARNISH INNER PT	Serviceable	81.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Bent	909.79 FL	*909.79 FL
19	1		*REAR BUMPER CENTRE RETAINER	Cracked	128.30 FL	*128.30 FL
20	1		*REAR BUMPER SIDE BRACKET (RH)	Repair	145.80 FL	*- FL
21	1		*REAR BUMPER SIDE BRACKET (LH)	Repair	145.80 FL	*- FL
22	1		*REAR BOOT SMART OPENER ANTENNA	Shorted	116.64 FL	*116.64 FL
23	1		*REAR BOOT SMART OPENER SENSOR	Dented	145.00 FL	*145.00 FL
24	1		*REAR END PANEL	Repair	524.88 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH	Serviceable	192.46 FL	*- FL
26	1		*RR EXHAUST TAIL PIPE CHROME RH	Serviceable	174.96 FL	*- FL
27	1		*RR EXHAUST TAIL PIPE CHROME LH	Serviceable	174.96 FL	*- FL
28	1		*REAR EXHAUST HEATSHIELD	Bent	93.31 FL	*93.31 FL
29	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
30	1		*REAR NUMBER PLATE AND CASE	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,100.23</b>	<b>5,580.23</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	499.01	276.01
<b>Total Parts (\$\$)</b>	<b>9,601.22</b>	<b>5,304.22</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,CUT-OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	800.00	500.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	800.00
3	TO APPLY UNDERSEALING	New	80.00	30.00
4	DIAGNOSE PROGRAM AND RESET SMART BOOT SYSTEM	New	380.00	150.00
5	TO REMOVE AND RENEW REVERSE SENSOR	New	50.00	50.00
6	WIRING CHARGES	New	60.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>2,370.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >