

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011589/EUY3E2

Date: 26/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00098182100
Claimant Vehicle No : SFW1801G **Insured Vehicle No :** GBK5817X
Date of Loss: 08/11/2021 Nature of Claim: TP Claim No: SNM21D206393/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFW1801G**
Make & Model: MERCEDES-BENZ A200, 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A) Engine No: 28291480227517
Reg. Date: 14/02/2020 (Man. Year: 2019) Chassis No: WDD1770872J126560
Colour: White Odometer: 16367 km
Engine Capacity: 1332 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Ventus 4 mm Rear Left Side: Ventus 4 mm
Front Right Side: Ventus 4 mm Rear Right Side: Ventus 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,857.17	4,560.93	4,296.24	48.51
Miscellaneous Items	540.00	70.00	470.00	87.04
Labour	4,450.00	1,300.00	3,150.00	70.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,847.17	5,930.93	7,916.24	57.17
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	13,847.17	4,750.00	9,097.17	65.70
+ GST 7.00/7.00% (S\$)	969.30	332.50	636.80	65.70
Nett Amount (S\$)	14,816.47	5,082.50	9,733.97	65.70

INSPECTION

Date of Assignment: 12/11/2021 Present Location: Cheng Auto Bodyworks (HQ)
Date Inspected: 15/11/2021 Inspected At: Cheng Auto Bodyworks (HQ)
5 Soon Lee Street #01-62 Pioneer Point
Singapore 627607
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2021)

Parts: 144 MERCEDES-BENZ A200 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFW1801G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR GLASS WITH MOULDING	Not Necessary	1,082.90 FL	*- FL
2	1	NA	*TAILGATE	Dented	2,045.10 FL	*2,045.10 FL
3	1	NA	*TAILGATE HINGE RH	Not Necessary	127.30 FL	*- FL
4	1	NA	*TAILGATE HINGE LH	Not Necessary	127.30 FL	*- FL
5	1	NA	*TAILGATE ABSORBABLE RH	Not Necessary	127.30 FL	*- FL
6	1	NA	*TAILGATE ABSORBABLE LH	Not Necessary	127.30 FL	*- FL
7	1	NA	*TAILGATE LOCK ASSY	Bent	33.50 FL	*33.50 FL
8	1	NA	*TAILGATE LOGO	Necessary	66.30 FL	*66.30 FL
9	1	NA	*EMBLEM	Necessary	99.50 FL	*99.50 FL
10	1	NA	*REFLECTOR LAMP RH	Not Necessary	430.10 FL	*- FL
11	1	NA	*REFLECTOR LAMP LH	Not Necessary	430.10 FL	*- FL
12	1	NA	*ENDPANEL	Repair	1,083.50 FL	*- FL
13	1	NA	*REINFORCEMENT	Bent	546.90 FL	*546.90 FL
14	1	NA	*REAR BUMPER	Dented	1,359.10 FL	*1,359.10 FL
15	1	NA	*REAR BUMPER BRACKET RH	Not Necessary	99.50 FL	*- FL
16	1	NA	*REAR BUMPER BRACKET LH	Not Necessary	99.50 FL	*- FL
17	1	NA	*REAR BUMPER REFLECTOR RH	Not Necessary	55.20 FL	*- FL
18	1	NA	*REAR BUMPER REFLECTOR LH	Not Necessary	55.20 FL	*- FL
19	1	NA	*REAR BUMPER DIFFUSER	Crushed	276.30 FL	*276.30 FL
20	1	NA	*REAR BUMPER LOWER CHROME	Cut	176.80 FL	*176.80 FL
21	2	NA	*REAR PARKING SENSOR INNER	Shorted	464.20 FL	*464.20 FL
22	4	NA	*REAR OUTER PARKING SENSOR	Not Necessary	928.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,841.30	5,067.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	984.13	506.77
Total Parts (\$\$)	8,857.17	4,560.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BUMPER CLIPS (NECESSARY)	100.00	30.00
2	1	NO PLATE (NOT NECESSARY)	40.00	0.00
3	1	SEALANT END PANEL (NOT NECESSARY)	100.00	0.00
4	1	SEALANT GLASS (NECESSARY)	100.00	40.00
5	4	SENSOR BRACKET (NOT NECESSARY)	200.00	0.00
Sub Total (\$\$)			540.00	70.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,400.00	500.00
2	SPRAYPAINTING	New	1,400.00	440.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	300.00	100.00
4	REMOVE AND REINSTALL UPHOLSTERY TO FACILITATE REPAIRS	New	300.00	0.00
5	ALIGNMENT	New	100.00	30.00
6	ANTI-RUST COATING AND APPLY CORROSION PROTECTION	New	300.00	30.00
7	REMOVE AND REPLACE REAR WINDSCREEN	New	150.00	120.00
8	DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW TAILGATE/FACILITATE REPAIR	New	200.00	80.00
9	GENERAL DIAGNOSTICS TO RESET RECALIBRATE USING ORIGINAL BMW SOFTWARE - HEADLAMP TAIL LIGHT SIDE MIRROR AND REVERSE SENSORS	New	300.00	0.00
Gross Labour Cost (\$\$)			4,450.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >