

Cheng Auto Bodyworks (Co. Reg. No 53315238X)5 Soon Lee Street #01-62 Pioneer Point
Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER:
CASA(S) Pte Ltd**China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	08/11/2021
Vehicle Reg. No.:	SFW1801G	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG CHUN KEONG (HUANG JUNQIANG)		
Make/Model:	MERCEDES-BENZ A200, 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A)	Vehicle Reg. Date:	14/02/2020
Vehicle Colour:	White	Chassis No:	WDD1770872J126560
Engine No:	28291480227517		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	8,857.17
Miscellaneous Items	540.00
Labour	4,450.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,847.17
+ GST 7.00% (S\$)	969.30
Nett Amount (S\$)	14,816.47

This claim is handled by: MURUGESAN S/O REGUNATHAN

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2021)

Parts: 144 MERCEDES-BENZ A200 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A1 Catalogue Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SFW1801G/11/11/2021 09:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR GLASS WITH MOULDING X nn	10.00	0.00	*1,082.90 FL
2	1	NA	*TAILGATE - 00	10.00	0.00	*2,045.10 FL
3	1	NA	*TAILGATE HINGE RH X nn	10.00	0.00	*127.30 FL
4	1	NA	*TAILGATE HINGE LH X nn	10.00	0.00	*127.30 FL
5	1	NA	*TAILGATE ABSORBABLE RH X nn	10.00	0.00	*127.30 FL
6	1	NA	*TAILGATE ABSORBABLE LH X nn	10.00	0.00	*127.30 FL
7	1	NA	*TAILGATE LOCK ASSY ? - BT	10.00	0.00	*33.50 FL
8	1	NA	*TAILGATE LOGO - APC	10.00	0.00	*66.30 FL
9	1	NA	*EMBLEM - APC	10.00	0.00	*99.50 FL
10	1	NA	*REFLECTOR LAMP RH X nn	10.00	0.00	*430.10 FL
11	1	NA	*REFLECTOR LAMP LH X nn	10.00	0.00	*430.10 FL
12	1	NA	*ENDPANEL X R ?	10.00	0.00	*1,083.50 FL
13	1	NA	*REINFORCEMENT ? - BT	10.00	0.00	*546.90 FL
14	1	NA	*REAR BUMPER - 00	10.00	0.00	*1,359.10 FL
15	1	NA	*REAR BUMPER BRACKET RH ? X nn	10.00	0.00	*99.50 FL
16	1	NA	*REAR BUMPER BRACKET LH ? X nn	10.00	0.00	*99.50 FL
17	1	NA	*REAR BUMPER REFLECTOR RH ? X nn	10.00	0.00	*55.20 FL
18	1	NA	*REAR BUMPER REFLECTOR LH ? X nn	10.00	0.00	*55.20 FL
19	1	NA	*REAR BUMPER DIFFUSER ? - CRV	10.00	0.00	*276.30 FL
20	1	NA	*REAR BUMPER LOWER CHROME - CRV	10.00	0.00	*176.80 FL
21	2	NA	*REAR PARKING SENSOR INNER 8 ? - Shorted	10.00	0.00	*464.20 FL
22	4	NA	*REAR OUTER PARKING SENSOR X nn	10.00	0.00	*928.40 FL

F=Franchise part. L=List/ItemDisc.

Sub Total (\$\$)

9,841.30

- List Item Discount on L Items (\$\$)

984.13

Total Parts (\$\$)

8,857.17

Cheng Auto Bodyworks/SFW1801G/11/11/2021 09:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

5067.70
-10%
4560.93 -

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BUMPER CLIPS ✓ n/c	30 100.00
2	1	NO PLATE X nn	40.00
3	1	SEALANT END PANEL X nn	100.00
4	1	SEALANT GLASS / n/c	40 100.00
5	4	SENSOR BRACKET X nn	200.00
70 Sub Total (S\$)			540.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR	New 500	1,400.00
2	SPRAYPAINTING	New 440	1,400.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New 100	300.00
4	REMOVE AND REINSTALL UPHOLSTERY TO FACILITATE REPAIRS	New X	300.00
5	ALIGNMENT	New 30	100.00
6	ANTI-RUST COATING AND APPLY CORROSION PROTECTION	New 30	300.00
7	REMOVE AND REPLACE REAR WINDSCREEN	New 120	150.00
8	DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW TAILGATE/FACILITATE REPAIR	New 80	200.00
9	GENERAL DIAGNOSTICS TO RESET RECALIBRATE USING ORIGINAL BMW SOFTWARE - HEADLAMP TAIL LIGHT SIDE MIRROR AND REVERSE SENSORS	New X	300.00
1300 -			
Gross Labour Cost (S\$)			4,450.00

Cheng Auto Bodyworks/SFW1801G/11/11/2021 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
15/11/21, 1-3pm

WML RL
L/S
My AL My
5 days

= 5930.93
L/S - 4744.74
= 4750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: