

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16016868/ARA3Q2-1
Date: 19/11/2021

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA040603
Claimant Vehicle No :	SKV3380L	Insured Vehicle No :	SDA7954Z
Date of Loss:	05/09/2016	Nature of Claim:	TP
		Claim No:	C0398810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV3380L		
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Engine No:	2ARU227793
Reg. Date:	14/09/2015 (Man. Year: 2015)	Chassis No:	MR053AK5004009314
Colour:	Blue	Odometer:	24188 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,478.80	3,606.85	3,871.95	51.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	580.00	2,170.00	78.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,228.80	4,186.85	6,041.95	59.07
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	10,228.80	3,200.00	7,028.80	68.72
+ GST 7.00/7.00% (S\$)	716.02	224.00	492.02	68.72
Nett Amount (S\$)	10,944.82	3,424.00	7,520.82	68.72
+ Loss of Use (3.0 x S\$180.00/day) (S\$)		540.00		
(S\$)		3,964.00		
Liabe Amount (50.00%) (S\$)		1,982.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		1,987.35		

INSPECTION

Date of Assignment: 06/09/2016

Date Inspected: 07/09/2016

Estimated Period of Repair: 4.0 days

Inspected At:

NEW HOCK TECK MOTOR WORKSHOP

Blk 1, Kaki Bukit Avenue 6 #01-43, AutoBay @ Kaki Bukit
Singapore 417883**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2017)
Parts:	143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV3380L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H HEAD LAMP (CONSISTENT)	Cracked	1,712.45 F	*1,712.45 FL
2	1		*FRONT L/H HEAD LAMP LOWER BRACKET (CONSISTENT)	Not Necessary	131.35 F	*- FL
3	1		*FRONT L/H HEAD LAMP TOP CHROME (CONSISTENT)	Not Necessary	132.10 F	*- FL
4	2		*FRONT L/H HEAD LAMP CLIPS (CONSISTENT)	Necessary	16.00 F	*16.00 FL
5	1		*FRONT GRILLE (CONSISTENT)	Cracked	372.85 F	*372.85 FL
6	1		*FRONT GRILLE EMBLEM LOGO (CONSISTENT)	Necessary	61.75 F	*61.75 FL
7	1		*FRONT GRILLE CHROME (CONSISTENT)	Not Necessary	289.90 F	*- FL
8	8		*FRONT GRILLE CLIPS (CONSISTENT)	Necessary	52.00 F	*20.00 FL
9	1		*FRONT L/H FENDER (CONSISTENT)	Repair	561.60 F	*- FL
10	1		*FRONT L/H FENDER DUAL VVT-I LOGO (CONSISTENT)	Necessary	61.85 F	*61.85 FL
11	1		*FRONT BUMPER (CONSISTENT)	Deformed	581.90 F	*581.90 FL
12	10		*FRONT BUMPER CLIPS (CONSISTENT)	Necessary	65.00 F	*30.00 FL
13	2		*FRONT BUMPER SENSOR (CONSISTENT)	Damaged	380.00 FS	*220.00 FS
14	1		*FRONT L/H BUMPER SIDE RETAINER (CONSISTENT)	Necessary	132.10 F	*48.00 FL
15	1		*FRONT L/H BUMPER AIR-DUCT (CONSISTENT)	Cut	182.25 F	*182.25 FL
16	1		*FRONT L/H BUMPER FOG LAMP (CONSISTENT)	Cracked	374.45 F	*374.45 FL
17	1		*FRONT L/H BUMPER FOG LAMP COVER (CONSISTENT)	Not Necessary	132.50 F	*- FL
18	1		*FRONT L/H BUMPER FOG LAMP COVER CHROME (CONSISTENT)	Cut	171.45 F	*171.45 FL
19	1		*FRONT L/H BUMPER MUD SHIELD (CONSISTENT)	Not Necessary	374.85 F	*- FL
20	6		*FRONT L/H BUMPER MUD SHIELD CLIPS (CONSISTENT)	Not Necessary	39.00 F	*- FL
21	1		*FRONT BUMPER CENTER CHROME MOULDING (CONSISTENT)	Not Necessary	172.10 F	*- FL
22	1		*FRONT BUMPER CENTER GARNISH (CONSISTENT)	Not Necessary	191.60 F	*- FL
23	8		*FRONT BUMPER CENTER GARNISH CLIPS (CONSISTENT)	Not Necessary	52.00 F	*- FL
24	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	372.85 F	*372.85 FL
25	1		*FRONT BUMPER INNER SPONGE (CONSISTENT)	Cracked	181.90 F	*181.90 FL
26	2		*FRONT BUMPER BRACKET (CONSISTENT)	Not Necessary	354.90 F	*- FL
27	1		*FRONT SUPPORT PANEL TOP GARNISH (CONSISTENT)	Deformed	289.10 F	*289.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS (CONSISTENT)	Necessary	39.00 F	*39.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					7,478.80	4,735.80
- List Item Discount on L Items 0.00/25.00% (\$)					0.00	1,128.95
Total Parts (\$)					7,478.80	3,606.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT SENSOR	New	100.00	50.00
2	TO CHECK WIRING	New	100.00	30.00
3	TUFF KOTE	New	150.00	0.00
4	PANEL BEATING	New	1,200.00	250.00
5	SPRAY PAINTING	New	1,200.00	250.00
Gross Labour Cost (S\$)			2,750.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >