Request for Mechanical Inspection Report

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg>

Fri 29/10/2021 11:01 AM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

- <Syed_Zayid_MUHAMMAD@spf.gov.sg>; Mohamed Yazid MOHAMMED YUSOFF (SPF)
- <Mohamed_Yazid_Mohammed_Yusoff@spf.gov.sg>; Syafiq HARRIS (SPF) <Syafiq_HARRIS@SPF.gov.sg>; Kia Huat YEO (SPF)
- <YEO_Kia_Huat@spf.gov.sg>; Rashidah AZMAN (SPF) <Rashidah_AZMAN@spf.gov.sg>; Adrian LIM (SPF)
- <Adrian_LIM@spf.gov.sg>; Abdul Muhaimin HUSSAIN (SPF) <Abdul_Muhaimin_HUSSAIN@spf.gov.sg>; Muhd Syarifuddin MUHAMMAD AJMAIN (SPF) <Muhd_Syarifuddin_Muhammad_Ajmain@spf.gov.sg>; Guang Hui LEE (SPF)
- $<\! LEE_Guang_Hui@spf.gov.sg>; Jocelyn LOH (SPF) <\! Jocelyn_Loh@spf.gov.sg> \\$

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the following **16 cases**. The ones marked in **red** are deemed to be **urgent**:

1	20211028			I
1			inspected:	
1	IP No.			
	TP/IP/45149/2021	On 15 September 2021 at about	SMM2275M -	IO Syed Zayid
		1830hrs, driver of motor car	Driver (Potential	
		SMM 2275 M was travelling	Defendant)	
		along New Upper Changi Road		
		towards Upper Changi Road		
		East. The motor car was		
		travelling in front of motor bus		
		PC 3031 K. The motor car had		
		allegedly applied unnecessary		
		braking multiple times which		
		eventually resulted in the motor		
		bus colliding into the rear of the		
		motor car. The driver of the		
		motor car claimed that there		
		was a problem to his motor car		
		which caused his motor car to		
		have intermittent power loss,		
		thus the reason that he had		
		reportedly slowed down and		
		picked up speed multiple times		
		while travelling in front of the		
		motor bus. The driver of the		
		motor car claimed that he does		
		not know what the problem was		
		with his motor car, but had		
		mentioned that there could be a		
		problem to the hybrid battery of		
		his motor car. For this incident,		
		an inspection to the motor car is		
		required to establish if there is		
		any mechanical fault to the		
		motor car, and to also separately		
		inspect the hybrid battery of the		
		motor car to establish if there is		
		any mechanical fault to the said		
		battery.		

2	TP/IP/45697/2021	On 27 September 2021	FBS5218H - Rider	DOC Yazid
_	,,,	(Saturday) 3.11 p.m., the	(Potential	
		motorcycle was travelling along	Defendant)	
		Serangoon Avenue 3 towards	,	
		Lorong Chuan after Serangoon		
		central Drive on lane 1 of a 2		
		lane road. Before the motorcycle		
		reached the pedestrian crossing,		
		he noticed that traffic light was		
		green light signal and a		
		pedestrian was crossing from his		
		left to right. When the		
		motorcycle was about 1		
		motorcar length distance before		
		the pedestrian crossing, the		
		motorcycle sounded honk, but		
		the pedestrian still proceed to		
		dash to the centre divider.		
		Hence, unable to stop in time,		
		the motorcycle's front portion		
		collided onto the pedestrian.		
Ī		Due to the accident, the		
		pedestrian was conveyed to Tan		
Ī		Tock Seng Hospital by		
		ambulance in a unconscious		
Ī		state, stand by due to head		
Ī		injuries and trauma spinal		
		injuries. The pedestrian		
		sustained head injuries, right		
		arm fracture, bleeding on her		
		feet and was conveyed to Tan Tock Seng Hospital where she		
		succumbed to his injuries. He		
		was pronounced dead at 5.28		
		p.m. by Dr Jasmine Lim Yen Yin.		
		A detailed mechanical		
		eliminate any mechanical fault		
		or any possible defence raised		
		by the Potential Defendant and		
		to rule out foul play.		
3	TP/IP/41065/2021	On the 28 August 2021	SH7598D - Driver	IO Ahmad
3	17/17/41003/2021	(Saturday) sometime around	(Potential	Syafiq
		7.13 p.m., the driver was driving	Defendant)	Syanq
		the motor taxi along CTE	Deletidant)	
		towards AYE slip road into Yio		
		Chu Kang Road. Driver claimed		
		that there was a fault with the		
		motor taxi's brake, which might		
		have caused him to collide onto		
		the rear of another vehicle (a		
		motorcycle). A detailed		
		mechanical inspection is		
		required to eliminate any		
		mechanical fault or any possible		
		defence raised by the Potential	1	

		Defendant and to rule out foul play.		
4	TP/IP/43533/2021	On 13/09/2021 at about 0010hrs, the driver of motorcar was making a right turn from Punggil Field into Punggol Road when he lose control of his vehicle and skidded to the right before colliding into 3 portions of the right side centre guard railings. Driver of SMR1861B claimed that the front right tyre of the motorcar had punctured before the accident which caused him to lose control. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.	SMR1861B - Driver (Potential Defendant)	SIO Kia Huat
5	TP/IP/47769/2021	On 6 October 2021 at about 2.05 p.m., an accident took place where a motor van was involved in a chain collision with 3 other vehicles along Pan Island Expressway towards the direction of Changi, 17 km. The driver of the motor van claimed that there was mechanical fault to the brakes and accelerator. Also, there was a warning sign stating "Accelerator and Brake pedals depressed simultaneously" that appeared in the vehicle prior to the accident. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.	GBG6849T - Driver (Potential Defendant)	SIO Rashidah
6-7	TP/IP/48709/2021	On 12 October 2021 sometime before 6.03 p.m., the Deceased was driving his lorry along PIE (AP) on lane 5 of 5 lanes road when he failed to keep a proper lookout ahead, collided onto the rear of motor lorry, which was stationary ahead. Driver of GBB4818Y was pronounced dead on the spot by attending SCDF paramedic with multiple injuries. A detailed mechanical	GBB4818Y - Driver (Deceased) XD568Z - Driver (Potential Defendant)	SIO Adrian Lim

		inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.		
8	TP/IP/47263/2021	On 4 October 2021 at about 1658hrs, the taxi moved off from stationary position at the taxi stand of Paya Lebar Square and collided into 3 parked motorcars. Victim was a rider who got caught in between the moving taxi and his motorbike. Hospital updated that victim is not doing well after his operations. The taxi was towed back on the same day as taxi driver informed that he only slightly pressed onto his accelerator but the taxi has a turbo that kicked in that causes him to lose control. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.	SHA8810B - Driver (Potential Defendant)	SIO Muhaimin
9	TP/IP/47281/2021	On the 4 October 2021 (Monday) at around 6.50 p.m., the driver was driving the van along Choa Chu Kang Avenue 4 towards the direction of Choa Chu Kang Way and had skidded to his right and collided into the centre guard railings. B1 cited that his brakes had failed and was not working prior to the said collision. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.	GP2118P - Driver (Potential Defendant)	IO Syarifuddin
10	TP/IP/45327/2021	On 22 September 2021 (Wednesday) at around 2.29 p.m., the driver was driving the said car on lane 3 of 3-lanes	SJZ7606B - Driver (Potential Defendant)	SIO Ken Lee

		road along BKE (PIE) when he suddenly swerved to his right. As a result, he collided into a motor car, SLC3773A, that was travelling straight on lane 2 and the said impact caused him to further collide in a lorry, GBF4111G, that was travelling straight ahead of him on lane 3. B1 cited that his steering wheel was jammed and suddenly gave way causing him to veer to the right prior to the said collision. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.		
11 - 12	TP/IP/25725/2021	On 25 May 2021 sometime before 9.24 a.m., the driver was driving at the said location when she collided onto the Deceased, who was cycling his bicycle across the pedestrian crossing, from her right to left. Deceased sustained multiple injuries and was conveyed to CGH. He succumbed to his injuries and was pronounced dead at 3.27pm on the same day at CGH. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.	SKS6639M - Driver (Potential Defendant) Bicycle – Pedal Cyclist (Deceased)	SIO Adrian Lim
13 - 14	TP/IP/45751/2021	On 26 September 2021 at about 9.40 a.m., the motorcycle was travelling straight along Tampines Avenue 10 towards Bartley Road East. At the signalised cross junction of Tampines Avenue 11, the motorcycle was proceeding straight while traffic light was green in his favour. Halfway doing so, the motorcar made a right turn from the motorcycle's opposite direction. Due to the impact, the 51-days old infant (motorcar's rear left passenger) succumbed to her injury and was pronounced dead by Dr Sammy Loh at 1510hrs in Changi General Hospital. A detailed	SJR926R - Driver (Potential Defendant) FX213E - Rider (Involved Party)	SIO Kamaliah

		mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the Potential Defendant and to rule out foul play.		
15	TP/IP/50125/2021	On 21 October 2021 sometime before 9.24 a.m., the Deceased was riding alone on his motor scooter, travelling straight along PIE (AP) near the 41 km marker on lane 1 of the 3-lane road when his motor scooter ran over a piece of wooden plank that was lying in the middle of lane 1. Due to that, the Deceased lost control of his motor scooter and skidded, veering to the left. The Deceased landed on lane 2 while his motor scooter landed on lane 3, near to the road shoulder. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	FBN5426A - Rider (Deceased)	SIO Kamaliah
16	TP/IP/51485/2021	On 29 Oct 2021 sometime before 12.51 a.m., the Deceased was riding his motorcycle along BKE(PIE) at the slip road into PIE(TUAS) when he lost control of his motorcycle and skidded to the right and collided into the Guard Railing. Deceased was pronounced dead at scene of accident at 1.10am by attending SCDF paramedic. To check motorcycle for any mechanical issues that may have caused or contributed to the accident. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence and to rule out foul play.	FY3218S - Rider (Deceased)	SIO Adrian

- 2. These request has been <u>approved</u> by my management.
- 3. Thank you, Sirs.

IO Zayid, DOC Yazid, IO Ahmad Syafiq, SIO Kia Huat, SIO Rashidah, SIO Adrian Lim, IO Muhaimin, IO Syarifuddin and SIO Ken Lee, as requested by you

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team Traffic Police Department | Singapore Police Force DID: (65) 6547 6435 | FAX: (65) 6547 6352





Singapore Police Force W police.gov.sg **FB** fb.com/singaporepoliceforce **IG** Instagram.com/singaporepoliceforce

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error.