

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011604/UTY3N2**Date:** 15/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00108272000

**Claimant Vehicle  
No :** SMV2703Y**Insured  
Vehicle No :** SJC504D

Date of Loss: 12/11/2021

Nature of Claim: TP

Claim  
No: SNM21D206514/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMV2703Y**

Make &amp; Model: MERCEDES-BENZ C180, 1.6 COUPE (R17 LED) (A) Engine No: 28291480345168

Reg. Date: 24/09/2020 (Man. Year: 2020)

Chassis No: W1K1183842N111358

Colour: Silver

Odometer: 18583 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45R18

Rear Tyre Size: 225/45R18

Front Left Side: Hankook 8 mm

Rear Left Side: Hankook 8 mm

Front Right Side: Hankook 8 mm

Rear Right Side: Hankook 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,044.80	2,645.69	1,399.11	34.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	855.00	725.00	45.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,624.80</b>	<b>3,500.69</b>	<b>2,124.11</b>	<b>37.76</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>(\$\$)</b>	5,624.80	2,800.00	2,824.80	50.22
<b>+ GST 7.00/7.00% (\$\$)</b>	393.74	196.00	197.74	50.22
<b>Nett Amount (\$\$)</b>	<b>6,018.54</b>	<b>2,996.00</b>	<b>3,022.54</b>	<b>50.22</b>

**INSPECTION**

Date of Assignment: 13/12/2021

Date Inspected: 15/11/2021

Inspected At: Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 13 Dec 2021)

**Parts:** M1-COUPE      MERCEDES-BENZ C180 1.6 COUPE (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMV2703Y)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Cut/Torn	1,950.00 FL	*1,795.21 FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	710.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR-LH	Not Necessary	48.00 FL	*- FL
4	1		*REAR BUMPER LOWER DIFFUSER	Grazed	650.00 FL	*650.00 FL
5	1		*REAR BUMPER EXHAUST CHROME-LH	Cut	195.00 FL	*195.00 FL
6	1		*REAR BUMPER CENTER CHROME MOULDING	Cracked	195.00 FL	*195.00 FL
7	2		*REAR BUMPER PARKING SENSOR	Serviceable	552.00 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	112.00 FL	*60.00 FL
9	1		*REAR NUMBER PLATE }	Dented	45.00 FS	*40.00 FS
10	1		*REAR NUMBER PLATE CASING }		29.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,486.00</b>	<b>2,935.21</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	441.20	289.52
<b>Total Parts (\$)</b>	<b>4,044.80</b>	<b>2,645.69</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING FUNCTIONS	New	120.00	25.00
2	TO RESET ELECTRICAL MODULE SYSTEM	New	380.00	80.00
3	TO RESPRAY AFFECTED AREAS	New	480.00	400.00
4	TO RENEW DAMAGED PARTS,STRAIGHTEN AND REPAIR & ALIGNED ALL PARTS	New	600.00	350.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,580.00</b>	<b>855.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >