



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : YN1212D

Accident Date : 13/11/2021

Location : FRESH DISTRIBUTION CENTRE NO 1 BUROH LANE

FE8SDJA20020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Model: MITSUBISHI FE85

30/7/2010


3P: YM2939P (CHINA TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Dented</i>	982.10	✓	
2	2 pcs	Front bumper o/s & n/s bracket <i>new</i>	506.20	+	
3	2 pcs	Front bumper o/s & n/s fog lamp <i>new</i>	306.20	+	
4	1 pc	Front grille (LOWER) <i>Crack</i>	698.20	✓	
5	1 pc	Front grille emblem <i>3/4</i>	102.21	✓	
6	1 pc	Front grille FUSO emblem <i>3/4</i>	89.20	✓	
7	7 pcs	Front grille clips <i>new</i>		42.00	30
8	2 pcs	Front o/s & n/s head-lamp <i>Crack</i>	1,280.00	✓	
9	2 pcs	Front o/s & n/s head-lamp lower seal <i>new</i>	78.20	+	
10	2 pcs	Front o/s & n/s lamp <i>Crack</i>	886.70 410.	+	
11	2 pcs	Front o/s & n/s signal lamp <i>new</i>	523.40	+	
12	1 pc	Front panel <i>Dented</i>	1,420.00 1324	+	
13	1 pc	Front panel garnish upper <i>Crack</i>	322.40	✓	
14	6pcs	Front panel garnish upper clips <i>new</i>		36.00	✓
15	1 pc	Front o/s door pillar panel <i>3/4</i>	696.20	+	
16	1 pc	Front reg. no. plate <i>Dented</i>		-45.00	30
17	1 pc	Air-cond blower <i>3/4 Crack</i>	1,018.60	✓	
18	1 pc	Air-cond cooling coil	1,662.00	✓	
19	2 pcs	Air-cond cooling coil pipe <i>new</i>	568.20	+	
20	1 pc	Air-con ducting <i>new</i>	780.00	+	
21	1 pc	Front o/s side mirror bracket <i>Best</i>	176.50	✓	
22	1 pc	Front o/s side mirror round <i>Dented</i>	70.40	✓	
		Sub-Total:	12,166.71	123.00	0.00
			25%	0%	0%
		After Less %:	9125.03	0.00	0.00
		Labour			
1		To straighten and welding & re align front o/s A pillar	1,600.00	1000	
2		To spray painting.	1,200.00	800	
3		To remove & replace air-cond blower & cooling coil. 2160	480.00	250	
4		To check wiring.	120.00	30	
5		To re-seal anti-rust.	80.00	✓	
		Sub-Total:	3,480.00		
		Total:	12,605.03		
		After Less 20%:	10,084.03		

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



AL 8778 1999
24 hr accident call



YN1212D ESTIMATEPg1