

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21011613/ETF3E2

Date: 28/12/2021

REFERENCE

Insured/Claimant:	NG PECK SAI	Policy No:	1800111855-02	Claim No:	7339454963SG
Date of Loss:	12/11/2021	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1172A	Engine No:	4B40DT6332
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)	Chassis No:	JMAXTGK1WJZ003436
Reg. Date:	19/09/2018 (Man. Year: 2018)	Odometer:	50306 km
Colour:	Silver		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,404.28	4,593.03	2,811.25	37.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	4,455.00	1,405.00	23.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,264.28	9,048.03	4,216.25	31.79
+ GST 7.00/7.00% (S\$)	928.50	633.36	295.14	31.79
Nett Amount (S\$)	14,192.78	9,681.39	4,511.39	31.79

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 15/11/2021 Inspected At:

Estimated Period of Repair: 9.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, RH	Broken	1,986.00 FL	*1,986.00 FL
3	1		*BRACKET, HEADLAMP	Not Necessary	16.00 FL	*- FL
4	1		*BRACKET, HEADLAMP	Not Necessary	12.00 FL	*- FL
5	1		*LAMP A, T/SIG & FOG, FR RH	Broken	506.00 FL	*506.00 FL
6	1		*HOSE ASSY, HEADLAMP WASHER	Not Necessary	185.00 FL	*- FL
7	1		*ACTUATOR, HEADLAMP WASHER, R	Not Necessary	113.00 FL	*- FL
8	1		*TANK, WINDSHIELD WASHER	Crushed	81.00 FL	*81.00 FL
9	1		*HORN, THEFT PROTECTION	Not Necessary	92.00 FL	*- FL
10	1		*FACE, FR BUMPER	Broken	718.00 FL	*718.00 FL
11	1		*COVER, FR BUMPER	Cut	382.00 FL	*382.00 FL
12	1		*BRKT, F/BMPR T/SIG LAMP, RH	Missing	17.00 FL	*17.00 FL
13	1		*GARNISH, FR BUMPER SIDE	Missing	77.00 FL	*77.00 FL
14	1		*GARNISH, FR BUMPER SIDE	Missing	214.00 FL	*214.00 FL
15	1		*REINFORCEMENT, FR BUMPER	Not Necessary	555.00 FL	*- FL
16	1		*REINF, FR BUMPER SIDE, RH	Not Necessary	35.00 FL	*- FL
17	1		*BRACKET, FR BUMPER SIDE, RH	Missing	18.00 FL	*18.00 FL
18	2		*BRKT, F/BMPR T/SIG LAMP, LH	Not Necessary	34.00 FL	*- FL
19	1		*EXTENSION, FR BUMPER	Not Necessary	318.00 FL	*- FL
20	1		*GRILLE ASSY, RADIATOR	Not Necessary	486.00 FL	*- FL
21	1		*COVER, FR BUMPER GRILLE	Not Necessary	302.00 FL	*- FL
22	1		*HOOD	Dented	787.00 FL	*787.00 FL
23	1		*WEATHERSTRIP, HOOD	Torn	84.00 FL	*84.00 FL
24	1		*HINGE, HOOD, RH	Not Necessary	47.00 FL	*- FL
25	1		*HINGE, HOOD, LH	Not Necessary	47.00 FL	*- FL
26	1		*INSULATOR, HOOD	Not Necessary	160.00 FL	*- FL
27	1		*LATCH, HOOD	Not Necessary	128.00 FL	*- FL
28	1		*COVER, HOOD LATCH	Not Necessary	18.00 FL	*- FL
29	1		*FENDER, FR RH	Dented	541.00 FL	*541.00 FL
30	1		*INSULATOR, FR FENDER, RH	Torn	52.00 FL	*52.00 FL
31	1		*COVER, HOOD LATCH	Not Necessary	18.00 FL	*- FL
32	1		*FENDER, FR RH	Not Necessary	541.00 FL	*- FL
33	1		*INSULATOR, FR FENDER, RH	Not Necessary	52.00 FL	*- FL
34	1		*PLATE, FR SIDEMEMBER, RH	Not Necessary	60.00 FL	*- FL
35	1		*PNL, HEADLAMP SUPT, UPR RH	Not Necessary	59.00 FL	*- FL
36	1		*SHIELD, FR WHEELHOUSE, RH	Torn	135.00 FL	*135.00 FL
37	1		*GARNISH, SIDE SILL, RH	Not Necessary	91.00 FL	*- FL
38	1		*MOULDING, FR WHEEL ARCH, RH	Crushed	151.00 FL	*151.00 FL
39	1		*TANK ASSY, RADIATOR COND	Not Necessary	60.00 FL	*- FL
40	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	172.00 FL	*- FL
41	1		*HOSE, W/SHLD WSHR TANK FLR	Not Necessary	24.00 FL	*- FL
42	1		*COVER, FR DECK, RH	Missing	17.00 FL	*17.00 FL
			(Supplementary)			
43	1		*CLIPS(X10)	Necessary	30.00 FL	*30.00 FL
			(Supplementary)			
44	1		*CLIPS(X10)	Necessary	20.00 FL	*20.00 FL
			(Supplementary)			
45	1		*GARNISH, FR PILLAR, RH	Broken	123.00 FL	*123.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,604.00	5,959.00
- List Item Discount on L Items 23.00/23.00% (\$)	2,199.72	1,365.97
Total Parts (\$)	7,404.28	4,593.03

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, BONNET, FRT RH FENDER, SUPPORT & AFFECTED AREA. REPAIR ON FRT RH FENDER INNER	New	2,700.00	1,575.00
2	PAINT WORK ON FRT BUMPER, BONNET, FRT RH FENDER, FRT RH FENDER INNER & FRT RH DOOR	New	1,750.00	1,750.00
3	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	0.00
4	TO TOP UP AIRCON GAS	New	80.00	0.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
6	PERFORM RUST PREVENTION	New	80.00	40.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
10	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR	New	80.00	80.00
11	RESPRAY LH FRONT FENDER & RH FRONT PILLAR (Supplementary)	New	700.00	700.00
Gross Labour Cost (\$)			5,860.00	4,455.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >