



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /NG PECK SAI Reg No/Reg Date SME1172A / 19/09/201 Date In/Mileage 13/11/2021/ 0 Chassis No JMAXTGK1WJZ003436 Engine No 4B40DT6332 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS ( ) Colour/Trim UO2 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	15/11/2021/ 12:59	BLK	282 / Kevin Leong	17414
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER, BONNET, FRT RH FENDER, SUPPORT & AFFECTED AREA	3.5	450		1575 2700.00
	REPAIR ON FRT RH FENDER INNER				
E PNT98000	PAINT WORK ON FRT, BUMPER, BONNET, FRT RH FENDER, FRT RH FENDER INNER & FRT RH DOOR	5	350		1750.00
E PNT88000	REMOVE & INSTALL FRT PARKING ASSIST FOR FACILITATE REPAIR				80.00
E PNT88000	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00
A 55900099	TO TOP UP AIRCON GAS				80.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA				40 80.00
M SUNDRY	PERFORM RUST PREVENTION				40 80.00
B WHEELALIGNMENT	To Conduct Computerize Full Wheel Alignment				120.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRIES	SUNDRIES				20 40.00
M HEADLAMP ASSY, RH		1.00	1986.00	23.00	1529.22
M BRACKET, HEADLAMP		1.00	16.00	23.00	12.32
M BRACKET, HEADLAMP		1.00	12.00	23.00	9.24
M LAMP A, T/SIG & FOG, FR RH		1.00	506.00	23.00	389.62
M HOSE ASSY, HEADLAMP WASHER		1.00	185.00	23.00	142.45
M ACTUATOR, HEADLAMP WASHER, R		1.00	113.00	23.00	87.01
M TANK, WINDSHIELD WASHER		1.00	81.00	23.00	62.37
M HOSE, W/SHLD WSHR TANK FLR		1.00	24.00	23.00	18.48
M HORN, THEFT PROTECTION		1.00	92.00	23.00	70.84

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /NG PECK SAI Reg No/Reg Date SME1172A / 19/09/201 Date In/Mileage 13/11/2021/ 0 Chassis No JMAXTGK1WJZ003436 Engine No 4B40DT6332 Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS ( ) Colour/Trim U02 STERLING SILVER/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	15/11/2021/ 12:59	BLK	282 / Kevin Leong	17414
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FACE,FR BUMPER	UK	1.00	718.00	23.00	552.86
M COVER,FR BUMPER	(Black) - LUT	1.00	382.00	23.00	294.14
M BRKT,F/BMPR T/SIG LAMP,RH	- MIS	1.00	17.00	23.00	13.09
M GARNISH,FR BUMPER SIDE	- MIS	1.00	77.00	23.00	59.29
M GARNISH,FR BUMPER SIDE	- MIS	1.00	214.00	23.00	164.78
M REINFORCEMENT,FR BUMPER	? X nn	1.00	555.00	23.00	427.35
M REINF,FR BUMPER SIDE,RH	? X nn	1.00	35.00	23.00	26.95
M BRACKET,FR BUMPER SIDE,RH	- MIS	1.00	18.00	23.00	13.86
M BRKT,F/BMPR T/SIG LAMP,LH	? X nn	2.00	17.00	23.00	26.18
M EXTENSION,FR BUMPER	? X nn	1.00	318.00	23.00	244.86
M GRILLE ASSY,RADIATOR	? X nn	1.00	486.00	23.00	374.22
M COVER,FR BUMPER GRILLE	? X nn	1.00	302.00	23.00	232.54
M HOOD	- DD	1.00	787.00	23.00	605.99
M WEATHERSTRIP,HOOD	- TN	1.00	84.00	23.00	64.68
M HINGE,HOOD,RH	X nn	1.00	47.00	23.00	36.19
M HINGE,HOOD,LH	X nn	1.00	47.00	23.00	36.19
M INSULATOR,HOOD	X nn	1.00	160.00	23.00	123.20
M LATCH,HOOD	X nn	1.00	128.00	23.00	98.56
M COVER,HOOD LATCH	X nn	1.00	18.00	23.00	13.86
M FENDER,FR RH	- DD	1.00	541.00	23.00	416.57
M INSULATOR,FR FENDER,RH	- TN	1.00	52.00	23.00	40.04
M COVER,HOOD LATCH	X nn	1.00	18.00	23.00	13.86
M FENDER,FR RH	X nn	1.00	541.00	23.00	416.57
M INSULATOR,FR FENDER,RH	X nn	1.00	52.00	23.00	40.04
M PLATE,FR SIDEMEMBER,RH	? X nn	1.00	60.00	23.00	46.20
M PNL,HEADLAMP SUPT,UPR RH	? X nn	1.00	59.00	23.00	45.43
M PANEL,HEADLAMP SUPPORT,UPR	? X nn	1.00	172.00	23.00	132.44
M SHIELD,FR WHEELHOUSE,RH	- TN	1.00	135.00	23.00	103.95
M GARNISH,SIDE SILL,RH	? X nn	1.00	91.00	23.00	70.07
M MOULDING,FR WHEEL ARCH,RH	- CRU	1.00	151.00	23.00	116.27
M TANK ASSY,RADIATOR COND	? X nn	1.00	60.00	23.00	46.20

Confirm &amp; accepted by

LKK Auto Consultants hence

the Repairer of the followings:

resurvey before/after spray painting

on damaged part(s) due to accident

We are subject to conditions

Authorized signatory and company stamp

Steve (LKK)  
15/11/21, 3pm  
DD- AL, AL  
E. X. C. - ?

P/P

My Bel sy  
9 days

Nett	12,417.98
7% GST on	869.26
<b>Total Payable</b>	<b>13,287.24</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.