

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | | | |
|---------------------------------------|---------------------------|------------------------------------|--|--|
| AIG Asia Pacific Insurance Pte. | Cust No/Name | /NG PECK SAI | | |
| Ltd. | Reg No/Reg Date | SME1172A / 19/09/201 | | |
| MOTOR CLAIM DEPT | Date In/Mileage | 13/11/2021/ 0 | | |
| 78 SHENTON WAY #09-16 AIG BUILDING | Chassis No | JMAXTGK1WJZ003436 | | |
| SINGAPORE 079120 | Engine No | 4B40DT6332 | | |
| Contact No 6419 1892 | Make/Model | MIT/ECLIPSE CROSS 1.5 T/C SPORTS (| | |
| | Colour/Trim | UO2 STERLING SILVER/ BK BLACK | | |

| Account No | Terms | Date/Time Printed | CSE | Operator | | WIP No | | |
|--------------------------|------------|--------------------------------------|-------------------------------|-----------------------|--------|------------------|-------|---------------|
| KAX00008 | Credit | 15/11/2021/ 12:59 | BLK | 282 / Kevin Leong | 9 | 17414 | | |
| | | Description of Good | s / Service | S | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | COT DUMOS | | | | S | | | 2700.0 |
| DEDATE O | LKI RAWAF | R, BONNET, FRT RH FI FENDER INNER | ENDER, SU | PPORT & AFFECTED AREA | A | | | |
| E PNT98000 | IN INI KII | FENDER INNER | | | | | | 1750 0 |
| | RK ON FRI | BUMPER , BONNET, FI | RT RH FEN | DER, FRT RH FENDER II | NNFR | | | 1750.0 |
| & FRT RE | DOOR | | sels senso do n te | , | | | | |
| E PNT88000 | | | | | | | | 80.0 |
| E PNT88000 | INSTALL | FRT PARKING ASSIST | FOR FACIL | ITATE REPAIR | | | | |
| | INSTALL | RADIATOR, CONDENSER | EUD EVCT | I ITATE DEDATE | | | | 120.0 |
| A 55900099 | INSTALL | INDIATOR, COMBENSER | TOK TACI | LITATE REPAIR | proof. | | | 80.0 |
| | P AIRCON | GAS | 247 | i roa | 45 | | | 00.0 |
| M SUNDRY | | | 511 | ima | | | | 80.0 |
| TO APPLY | SEALANT | ON AFFECTED AREA | 96 | | .60 | フ | | |
| M SUNDRY PERFORM | RUST PREV | | | | | | | 80.0 |
| B WHEELALIG | | LIVITON | - 12 | | | | | 120.0 |
| | | erize Full Wheel Ali | gnment | | | | | 120.0 |
| A 54900099 | | | | | | | | 30.0 |
| | RING & CH | ASSIS ELECTRICAL SYS | STEM | | | | | |
| A 10028901 | OUT DIAG | NOSTIC CHECK ON ELEC | TDONTO C | ONTDOL CYCTEM | | | | 120.0 |
| M SUNDRY | OUT DIAG | INUSTIC CHECK ON ELEC | JIKUNIC CO | UNIKOL SYSIEM | | | | 40.0 |
| SUNDRIES | | | | | | | | 40.0 |
| M HEADLAMP | | | | | 1.00 | 1986.00 | 23.00 | 1529.2 |
| M BRACKET, | | | | | 1.00 | | 23.00 | 12.3 |
| M BRACKET, M LAMP A.T | /SIG & FO | C ED DU | | | 1.00 | | 23.00 | 9.2 |
| | Y,HEADLAM | | | | 1.00 | 506.00 | | 389.6 |
| | | WASHER, R | | | 1.00 | 185.00 113.00 | | 142.4 87.0 |
| | DSHIELD W | | | | 1.00 | | 23.00 | 62.3 |
| | HLD WSHR | | | | 1.00 | | 23.00 | 18.4 |
| M HORN, THE | FT PROTEC | TION | | | 1.00 | | 23.00 | 70.8 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | | | |
|----------------------------------|---------------------------|------------------------------------|--|--|
| AIG Asia Pacific Insurance Pte. | Cust No/Name | /NG PECK SAI | | |
| Ltd. | Reg No/Reg Date | SME1172A / 19/09/201 | | |
| MOTOR CLAIM DEPT | Date In/Mileage | 13/11/2021/ 0 | | |
| 78 SHENTON WAY #09-16 | Chassis No | JMAXTGK1WJZ003436 | | |
| AIG BUILDING SINGAPORE 079120 | Engine No | 4B40DT6332 | | |
| Contact No 6419 1892 | Make/Model | MIT/ECLIPSE CROSS 1.5 T/C SPORTS (| | |
| | Colour/Trim | UO2 STERLING SILVER/ BK BLACK | | |

| Account No | Terms | Date/Time Pr | inted | CSE | Ope | rator | | WIP No | | |
|---|--------------------|--------------|----------|--------------|-----|---------------|----------|---------------------------|-------|-------------------|
| 80000XA | Credit | 15/11/2021/ | 12:59 | BLK | 282 | / Kevin Leong | | 17414 | | |
| | | Description | of Goods | S / Services | | | Qty | Unit Price | Disc% | Amount |
| M FACE, FR | BUMPER | | | | | | 1.00 | 718.00 | 23.00 | 552.86 |
| | R BUMPER | | | | | | 1.00 | 382.00 | 23.00 | 294.14 |
| | BMPR T/SIG | | | | | | 1.00 | 17.00 | 23.00 | 13.09 |
| | FR BUMPER | | | | | | 1.00 | | 23.00 | 59.29 |
| | FR BUMPER | | | | | | 1.00 | 214.00 | | 164.78 |
| | CEMENT, FR | | | | | | 1.00 | 555.00 | 23.00 | 427.35 |
| U.S. 200200000000000000000000000000000000 | R BUMPER S | | | | | | 1.00 | 35.00 | 23.00 | 26.95 |
| M BRACKET | FR BUMPER | R SIDE, RH | | | | | 1.00 | 18.00 | 23.00 | 13.86 |
| M BRKT,F/ | BMPR T/SIG | G LAMP, LH | | | | | 2.00 | 17.00 | 23.00 | 26.18 |
| | ON,FR BUMF | | | | | | 1.00 | 318.00 | 23.00 | 244.86 |
| | ASSY,RADI <i>A</i> | ATOR | | | | 1 | 1.00 | 486.00 | 23.00 | 374.22 |
| M COVER,F | R BUMPER G | GRILLE | | 2550 | IT | mai | 1.00 | 302.00 | 23.00 | 232.54 |
| M HOOD | | | _ (| 5111 | 111 | 1111211 | 1.00 | 787.00 | 23.00 | 605.99 |
| M WEATHER | STRIP, HOOD | | 7 | | | 11 11 (21) | 4.00 | 84.00 | 23.00 | 64.68 |
| M HINGE,H | OOD,RH | | | | | | 1.00 | 47.00 | 23.00 | 36.19 |
| M HINGE, H | OOD,LH | | | | | | 1.00 | 47.00 | 23.00 | 36.19 |
| M INSULAT | OR,HOOD | | | | | | 1.00 | 160.00 | 23.00 | 123.20 |
| M LATCH,H | 00D | | | | | | 1.00 | 128.00 | 23.00 | 98.56 |
| M COVER, H | OOD LATCH | | | | | | 1.00 | 18.00 | 23.00 | 13.86 |
| M FENDER, | FR RH | | | | | | 1.00 | 541.00 | 23.00 | 416.57 |
| M INSULAT | OR, FR FEND | DER,RH | | | | | 1.00 | 52.00 | 23.00 | 40.04 |
| M COVER, H | OOD LATCH | | | | | | 1.00 | 18.00 | 23.00 | 13.86 |
| M FENDER, | FR RH | | | | | | 1.00 | 541.00 | | 416.57 |
| M INSULAT | OR, FR FEND | DER,RH | | | | | 1.00 | | 23.00 | 40.04 |
| | R SIDEMEME | | | | | | 1.00 | | 23.00 | 46.20 |
| | DLAMP SUPT | | | | | | 1.00 | | 23.00 | 45.43 |
| | | JPPORT, UPR | | | | | 1.00 | 172.00 | | 132.44 |
| | FR WHEELHO | | | | | | 1.00 | 135.00 | | 103.95 |
| | ,SIDE SILI | | | | | | 1.00 | | 23.00 | 70.07 |
| | G,FR WHEEL | | | | | | 1.00 | 151.00 | | 116.27 |
| | SY, RADIATO | | | | | | 1.00 | | 23.00 | 46.20 |
| Confirm & | accepted b | ру | | | | | | 500 A COLOR SECTION 1 | | 2000-200 |
| | • | | | | | 79 | % GST on | Ne ⁻ 12417. | | 12,417.9 869.2 |
| | | | | | | | | tal Payab | | 13,287.2 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.