

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011614/UEA3Q2**Date:** 28/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000767_01

Claimant Vehicle No : SDV2272E **Insured Vehicle No :** GZ1281D

Date of Loss: 12/11/2021 Nature of Claim: TP Claim No: MFL2021D0004978

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDV2272E**

Make & Model: TOYOTA COROLLA, AXIO 1.5 X (A) Engine No: 2NR8712067

Reg. Date: 21/12/2016 (Man. Year: 2016) Chassis No: NRE1610024246

Colour: Grey Odometer: 222565 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15

Front Left Side: Comfort Contact 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Comfort Contact 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,235.07	3,470.15	764.92	18.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	2,160.00	755.00	25.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,150.07	5,630.15	1,519.92	21.26
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	7,150.07	5,050.00	2,100.07	29.37
+ GST 7.00/7.00% (S\$)	500.50	353.50	147.00	29.37
Nett Amount (S\$)	7,650.57	5,403.50	2,247.07	29.37
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		6,003.50		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 15/11/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jan 2022)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDV2272E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BBOTLID	Dented / Bent	754.30 FL	*754.30 FL
2	1		*REAR BBOTLID INSULATOR	Not Necessary	197.70 FL	*- FL
3	10		*REAR BBOTLID INSULATOR CLIPS	Not Necessary	51.00 FL	*- FL
4	2		*REAR BBOTLID HINGE	Serviceable	213.60 FL	*- FL
5	1		*REAR BBOTLID WEATHERSTRIP (RUBBER)	Twisted	185.20 FL	*185.20 FL
6	1		*REAR BBOTLID BADGE	Necessary	52.20 FL	*52.20 FL
7	1		*REAR BBOTLID COROLLA EMBLEM	Necessary	43.30 FL	*43.30 FL
8	1		*REAR BBOTLID AXIO EMBLEM	Necessary	44.20 FL	*44.20 FL
9	1		*REAR NUMBER PLATE GARNISH (CHROME)	Scratched / Cracked	332.20 FL	*332.20 FL
10	2		*REAR NUMBER PLATE LAMP	Not Necessary	145.80 FL	*- FL
11	2		*REAR TAIL LAMP	Cracked	1,150.60 FL	*1,064.20 FL
12	1		*RREAR FLOOR PANEL TOP BOARD	Warped / Cracked	319.80 FL	*319.80 FL
13	1		*REAR BUMPER	Distorted	530.80 FL	*530.80 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Bent	226.60 FL	*170.00 FL
16	2		*REAR BUMPER RED REFLECTOR	Not Necessary	108.80 FL	*- FL
17	1		*END PANEL	Badly Dented	602.10 FL	*602.10 FL
18	1		*END PANEL TOP GARNISH	Twisted	218.90 FL	*218.90 FL
19	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
20	1		*REAR LH FENDER (NPA)	Repair	0.00 FL	*- FL
21	1		*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL
22	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*NUMBER PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,540.10	4,560.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,305.03	1,090.05
Total Parts (\$\$)	4,235.07	3,470.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	1,280.00	1,100.00
2	TO REMOVE AND REFIX CARPET & GARNISHES	New	120.00	80.00
3	LABOUR CHARGES	New	1,280.00	850.00
4	TUFF COAT	New	120.00	60.00
5	WIRING	New	35.00	20.00
6	LABOUR FOR R&R REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (\$)			2,915.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >