

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CC4/1112101/6144003

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SDV 2272E
at Workshop m/s: J.n Auto
of _____
Insured: 6/2/2810
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SDV 2272E Yr Regn: 21/12/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota Corolla Axio c.c. 1496
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 222565 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: NRE1610024246
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 175/65 R15 comfort
R: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: \$ 48k.
IDAC Accident Rport: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 25 10 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: LYA 31797
Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FALKEN
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 12/11/21 D.O.I. 15/11/21
Survey held at _____
Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 9500
note new parts replacement no second hand parts
27/11/21 Repair - sum \$ 5050 confirmed with Jones

Date/Time, File Pass to? : Preli. Report
 : Final Report
1) _____
Date/Time, File Return to?
2) _____
Report Format :
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
Resurvey No. of Trip: _____ Survey Fee: _____
Transportation: _____
Add Fee: : Site Insp (\$ _____)) S + RS, SI
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))
TOTAL _____

Repair sum 850.50

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

15/11/2021

M/S INDIA INTERNATIONAL INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA AXIO - SDV2272E

DOA : 12/11/2021

not Authorized
then
15/11/21
~~4/5 \$4500~~
whichever the repair
5 days.

S/N	QTY	DESCRIPTION		
1	1 PC	REAR BOOTLID	20/seat	\$ 754.30 ✓
2	1 PC	REAR BOOTLID INSULATOR	an	\$ 197.70 X
3	10 PCS	REAR BOOTLID INSULATOR CLIPS	an	\$ 51.00 X
4	2 PCS	REAR BOOTLID HINGE	su	\$ 213.60 X
5	1 PC	REAR BOOTLID WEATHERSTRIP (RUBBER)	7m1	\$ 185.20 ✓
6	1 PC	REAR BOOTLID BADGE	ner	\$ 52.20 ✓
7	1 PC	REAR BOOTLID "COROLLA" EMBLEM	ner	\$ 43.30 ✓
8	1 PC	REAR BOOTLID "AXIO" EMBLEM		\$ 44.20 ✓
9	1 PC	REAR NUMBER PLATE SE GARNISH	chrome scrf	\$ 332.20 ✓
10	2 PCS	REAR NUMBER PLATE LAMP	an	\$ 145.80 X
11	2 PCS	REAR TAIL LAMP	one 532.10 x 2 = 1064	\$ 20 1150.60 ✓
12	1 PC	REAR floor panel top board	waped lene	\$ 319.80 ✓
13	1 PC	REAR BUMPER	dis	\$ 530.80 ✓
14	1 set 10 PCS	REAR BUMPER CLIPS	ner	\$ 43.00 ✓
15	2 PCS	REAR BUMPER SIDE RETAINER	seat 85x2=170	\$ 226.60 ✓
16	2 PCS	REAR BUMPER RED REFLECTOR	an	\$ 108.80 X
17	1 PC	END PANEL	body 500	\$ 602.10 ✓
18	1 PC	END PANEL TOP GARNISH	7m1	\$ 218.90 ✓
19		SPARE TYRE PANEL		\$ REPAIR X
20		REAR LH FENDER		\$ REPAIR X
21		REAR RH FENDER		\$ REPAIR X
				\$ 5220.10
			Disc -25%	\$ -1305.03
				\$ 3915.07

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

15/11/2021

M/S INDIA INTERNATIONAL INSURANCE

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA AXIO - SDV2272E

DOA : 12/11/2021

S/N	QTY	DESCRIPTION		
22		SPRAY PAINTING	\$	1280.00 <i>1100</i>
23		L/B TO REMOVE AND REFIX CARPET & GARNISHES	\$	120.00 <i>80</i>
24		LABOUR CHARGES	\$	1280.00 <i>850</i>
25		TUFF COAT	\$	120.00 <i>60</i>
24		NUMBER PLATE	\$ <i>su</i>	40.00 <i>x</i>
25	<i>1 set</i>	REVERSE SENSOR	\$ <i>studied</i>	280.00 <i>200 S/W</i>
26		WIRING	\$	35.00 <i>-20</i>
27		LABOUR FOR REVERSE SENSOR <i>R&R</i>	\$	80.00 <i>-50</i>
			Total	\$ <u>7150.07</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 4360.20
252
P- 3270.15
S.N- 200
L- 2160

5630.15
202
202
4804
2020