



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY			Ref: CC4/ASM21011615/Tps3q2 Date: 18/03/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3695P	Veh. Inspected	GBK 576Z	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M03M2Z	Excess (\$)	0.00	
Assign From		Assign Date	15/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GDH2012005513	Colour	SILVER	
Odometer	48639 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	ECOPIA	6 mm	
L/H Front Tyre	195/80 R15	ECOPIA	6 mm	
R/H Rear Tyre	195/80 R15	ECOPIA	6 mm	
L/H Rear Tyre	195/80 R15	ECOPIA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/11/2021	Inspection Date	15/11/2021	
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	